DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Acura	ADX	25-26			5517	VS20	VS20	Auto-relearn
Acura	CSX	08-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Acura	ILX	13-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	5513	7000K	VS70	OBDII required
Acura	ILX	16-18	7007HP	5003M (Program first)	5514	7000K	VS70	Auto-relearn
Acura	ILX	19-22			5517	VS20	VS20	Auto-relearn
Acura	Integra (snap-in)	23-26			5517	VS20	VS20	Auto-relearn
Acura	Integra Type S	24-26			3751	7000K	VS70	Auto-relearn
Acura	MDX	04-06	7002A or 7007HP	5003M (Program first)	1057	2000K	1096	Auto-relearn
Acura	MDX	07-13	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	MDX	14-15			5512	7000K	VS70	Auto-relearn
Acura	MDX	16-20	7007HP	5003M (Program first)	5514	7000K	VS70	Auto-relearn
Acura	MDX	22-26			5517	VS20	VS20	Auto-relearn
Acura	NSX	16-22			3751	7000K	VS70	Auto-relearn
Acura	RDX	07-12	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	RDX	13-15			5512	7000K	VS70	Auto-relearn
Acura	RDX	16-18	7007HP	5003M (Program first)	5514	7000K	VS70	Auto-relearn
Acura	RDX (clamp-in)	19-21			3751	7000K	VS70	Auto-relearn
Acura	RDX (snap-in)	21-26			5517	VS20	VS20	Auto-relearn
Acura	RL	05-08	7002A or 7007HP	5003M (Program first)	1057	2000K	1096	Auto-relearn
Acura	RL	09-12	7002A or 7007HP	5003M (Program first)	1057	2045K or 2000K	None or 1096	Auto-relearn
Acura	RLX	14-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1214	2045K	NO	Auto-relearn
Acura	RLX	16-20			5512	7000K	VS70	Auto-relearn
Acura	TL	06-08	7002A or 7007HP	5003M (Program first)	1057	2000K	1096	Auto-relearn
Acura	TL	09-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1214	2045K	NO	Auto-relearn
Acura	TLX	15-17	7007HP	5003M (Program first)	5514	7000K	VS70	Auto-relearn
Acura	TLX	18-20			3751	7000K	VS70	Auto-relearn
Acura	TLX	21-25			5517	VS20	VS20	Auto-relearn
Acura	TSX	07-14	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	ZDX	10-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1214	2045K	NO	Auto-relearn
Acura	ZDX	24-25			3166	VS20	VS20	Auto-relearn
Alfa Romeo	4C	15-20		5001 (Just relearn) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
Alfa Romeo	8C Competizione	09-10		5003M (Program first)	9001	1090K	1092 or 1094	
Alfa Romeo	Giulia	17-25	7008HP	5001 (Program first) or 5003M (Program first)	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Stelvio	18-25	7008HP	5001 (Program first) or 5003M (Program first)	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Tonale	23-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Aston Martin	DBX	21-25		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	Trigger required
Aston Martin	Vantage	19-21		5001 (Just relearn) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
Audi	Allroad	02-05		5003M (Program first)	9004	1090K	1092 or 1099L	No tools needed
Audi	A3	08-11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Audi	A4	05-08		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	A4 cabrio	09		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	A4 4-door	09	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Audi	A5	08-09	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Audi	A5 (clamp-in - B10)	25-26		5003M (Program first)	9597	1096	1096	No tools needed
Audi	A6	05-08		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	A6 (clamp-in)	22-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	A6 allroad	26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	A7 (clamp-in)	22-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	A8	02-03		5003M (Program first)	9004	1090K	1092	No tools needed
Audi	A8	04-09		5003M (Program first)	9001	1090K	1092	No tools needed
Audi	A8 (clamp-in)	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	e-tron crossover (clamp-in)	22-23		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	e-tron GT sedan	22-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	Q5	09	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Audi	Q5	25-26		5003M (Program first)	9597	1096	1096	Auto-relearn
Audi	Q7	07-09		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	Q7 (clamp-in)	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	Q8 and Q8 e-tron (clamp-in)	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	R8	08-09		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	R8	10-23		5003M (Program first)	9011	1096	1096	No tools needed
Audi	RS3	17-20		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	RS3	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	RS4	07-08		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	RS5	18-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	RS6	03		5003M (Program first)	9004	1090K	1092	No tools needed
Audi	RS6	21-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	RS7	14-18		5003M (Program first)	9011	1096	1096	No tools needed
Audi	RS7	21-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	RS e-tron GT	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	RS Q8	20-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	S4	05-09		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	S5	08-09	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Audi	S5 (clamp-in)	25-26		5003M (Program first)	9597	1096	1096	No tools needed
Audi	S6	07-09		5003M (Program first)	9011	1090K	1092	No tools needed
Audi	S6 (clamp-in)	22-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	S7 (clamp-in)	22-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	S8	02-03		5003M (Program first)	9004	1090K	1092	No tools needed
Audi	S8	07-09		5003M (Program first)	9001	1090K	1092	No tools needed
Audi	S8	16-18		5003M (Program first)	9011	1096	1096	No tools needed
Audi	S8	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	S e-tron GT sedan	25-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	SQ5	14-16		5001 (Program first) or 5003M (Program first)	9011	1096	1096	No tools needed
Audi	SQ5	25-26		5003M (Program first)	9597	1096	1096	Auto-relearn
Audi	SQ7 (clamp-in)	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	SQ8 (non-RS)	22-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Audi	TT	08-10	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Audi	TT RS	18-22		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Bentley	Arnage	02-03		5003M (Program first)	9001	1090K	1092-1095	
Bentley	Arnage	04-09		5003M (Program first)	9011	1090K	1092-1095	
Bentley	Azure	07-10		5003M (Program first)	9011	1090K	1092-1095	
Bentley	Bentayga	17-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	
Bentley	Brooklands Coupe	08-09		5003M (Program first)	9011	1090K	1092-1095	
Bentley	Continental GT	04-05		5003M (Program first)	9001	1090K	1092-1095	
Bentley	Continental GT (Post May 2005)	05-10		5003M (Program first)	9011	1090K	1092-1095	
Bentley	Continental GT	11-18		5003M (Program first)	9011	1096	1096	
Bentley	Continental GT	20-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	
Bentley	Continental GT	25		5003M (Program first)	9597	1096	1096	
Bentley	Flying Spur	06-10		5003M (Program first)	9011	1090K	1092-1095	

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

1

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Bentley	Flying Spur	11-18		5003M (Program first)	9011	1096	1096	
Bentley	Flying Spur	20-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	
Bentley	Flying Spur	25		5003M (Program first)	9597	1096	1096	
Bentley	Mulsanne	11-20		5003M (Program first)	9011	1096	1096	
BMW	1 Series	08-11		5003M (Program first)	1027	1090K	1092-1095	No tools needed
BMW	1 Series (Post Sept. 2010)	11-13		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	2 Series	14		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	2 Series 2dr (Post March 2014)	14-21	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	2 Series (4dr)	20-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	2 Series (2dr)	22-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	3 Series	02-06		5003M (Program first)	9002	1090K	1092-1095	No tools needed
BMW	3 Series	07-09		5003M (Program first)	1027	1090K	1091-1095	No tools needed
BMW	3 Series	10-11		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	3 Series 2dr. and Wagon	12-13		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	3 Series 4dr. Sedan	12-14		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	3 Series (Post March 2014)	14-18	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	3 Series Gran Turismo	19	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	3 Series wagon	19	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	3 Series sedan (non-M3)	19-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	4 Series	14		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	M4 GTS	15-17		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	4 Series (Post March 2014)	14-20	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	4 Series (not M4)	21-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	5 Series	06-11		5003M (Program first)	1027	1090K	1091-1095	No tools needed
BMW	5 Series (Post Sept. 2010)	11-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	5 Series (Post March 2014)	14-16		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	5 Series Gran Turismo	17		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	5 Series	17-23		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	5 Series	24-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	6 Series	06-10		5003M (Program first)	1027	1090K	1091-1095	No tools needed
BMW	6 Series	12-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	6 Series (non-G.T.)	14-19		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	6 Series Gran Turismo	18-19		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	7 Series	02-05		5003M (Program first)	9002	1090K	1092-1095	No tools needed
BMW	7 Series	06-11		5003M (Program first)	1027	1090K	1091-1095	No tools needed
BMW	7 Series (Post Sept. 2010)	11-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	7 Series (Post March 2014)	14-15		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	7 Series	16-22		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	7 Series	23-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	8 Series	19-25		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	i3	14-21	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	i4 and M	22-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	i5	24-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	i7	23-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	i8	14-20	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	iX and M	22-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	M2 - G42	23-25		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	M3	21-25		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	M4	21-25		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	X1	13-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	X1	15		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	X1	16-22	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	X1	23-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	X2	18-23	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	X2	24-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	X3	06-10		5003M (Program first)	1027	1090K	1091-1095	No tools needed
BMW	X3	11-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	X3	15-17		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	X3	18-24		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	X3	25		5001 (Program first) or 5003M (Program first)	9077	1096	1096'	No tools needed
BMW	X4	15-18		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	X4	19-25		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	X5	07-11		5003M (Program first)	1027	1090K	1092-1095	No tools needed
BMW	X5 (Post Oct. 2010)	11-13		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	X5	14-18	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	X5	19-23		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	X5	24-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	X6	08-11		5003M (Program first)	1027	1090K	1092-1095	No tools needed
BMW	X6 (Post Oct. 2010)	11-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	X6	15-19	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
BMW	X6	20-23		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	X6	24-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	X7	19-22		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	No tools needed
BMW	X7	23-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	XM	23-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
BMW	Z Series	07-11		5003M (Program first)	1027	1090K	1091-1095	No tools needed
BMW	Z Series (Post Sept. 2010)	11-14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
BMW	Z4	15-16		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
BMW	Z4	19-25		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
**	Note: 1099 and 1099L are valve options on some special wheel packages.							
BrightDrop	Zevo 400 and 600	22-24		5003R (Program first)	3166	VS20	VS20	
Buick	Allure	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Buick	Allure	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Cascada	16-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Enclave	08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Buick	Enclave	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Enclave	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Buick	Enclave	18-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Buick	Enclave	25-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Buick	Encore	13-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Encore	16-22	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Buick	Encore GX	20-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Buick	Envision	16-18	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Envision	19-20	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Buick	Envision	21-26		5003R (Program first)	3166'	VS950	VS950	Auto-relearn
Buick	Envista	24-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Buick	LaCrosse	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Buick	LaCrosse	08-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	LaCrosse	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Buick	LaCrosse	17-19	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Buick	Lesabre	07	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Lucerne	07-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Rainier	06-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
Buick	Regal	11-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Regal	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Buick	Regal and TourX	18-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Buick	Verano	12-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Buick	Verano	16-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Cadillac	ATS	13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	Discontinued	VS90	VS90	Trigger required
Cadillac	ATS	14-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	ATS (snap-in)	16-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Cadillac	ATS Performance	13	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	Discontinued	7020K	VS70	Trigger required
Cadillac	ATS Performance	14-15	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Cadillac	ATS Performance	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	2030K	VS40	Trigger required
Cadillac	ATS-V	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	2030K	VS40	Trigger required
Cadillac	Celestiq	25		5003M' (Program first)	8424	2030K	VS40	Auto-relearn
Cadillac	CT4	20-25		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	CT4-V	20-25		5003M (Program first)	8424	2030K	VS40	Auto-relearn
Cadillac	CT5	20-25		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	CT5-V	20-25		5003M (Program first)	8424	2030K	VS40	Auto-relearn
Cadillac	CT6 (315MHz)	16	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Cadillac	CT6 (433MHz)	16-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Cadillac	CT6 and V	19-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Cadillac	CT6-V	19-20	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
Cadillac	CTS	04-07	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
Cadillac	CTS	08-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	CTS	16-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Cadillac	CTS Vsport	14-15	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Cadillac	CTS Vsport	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	2030K	VS40	Trigger required
Cadillac	CTS-V	09-15	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Cadillac	CTS-V	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	2030K	VS40	Trigger required
Cadillac	Deville	01-05		5002 (Program first) or 5003M (Program first)	9117	1080K	NO	Trigger required
Cadillac	DTS	06	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Cadillac	DTS	07-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	ELR	14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	ELR	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Cadillac	Escalade	04		5002 (Program first) or 5003M (Program first)	9115	1070K	NO	Trigger required
Cadillac	Escalade	05-06	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9107	1070K	NO	Trigger required
Cadillac	Escalade	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
Cadillac	Escalade	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Cadillac	Escalade	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	Escalade	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Cadillac	Escalade	18-20	7006HPR or 7007HP	5003R (Program first)	6164	VS20	VS20	Trigger required
Cadillac	Escalade	21-25		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	Escalade Trailer TPMS	21-24	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	No tools needed
Cadillac	Lyriq with 20in OE wheels	23-24		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	Lyriq with 22in OE wheels (rear-facing sensor)	23-24		5003M (Program first)	NEW	2030K	NEW	Auto-relearn
Cadillac	Optiq	25		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	Seville	01-04		5002 (Program first) or 5003M (Program first)	9117	1080K	NO	Trigger required
Cadillac	SRX	04-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
Cadillac	SRX	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	STS	05-08	7001HP	5002 (Program first) or 5003M (Program first)	9076	1070K	NO	Trigger required
Cadillac	STS	09-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	STS-V	09	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Cadillac	Vistiq with 21in or 22in OE wheels	26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	Vistiq with 23in OE wheels (rear-facing sensor)	26		5003M (Program first)	NEW	2030K	NEW	Auto-relearn
Cadillac	XLR	04-09	7001HP	5002 (Program first) or 5003M (Program first)	9076	1070K	NO	Trigger required
Cadillac	XT4	19-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Cadillac	XT4	24-25		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	XT5	17	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Cadillac	XT5	18-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Cadillac	XT6	20-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Cadillac	XTS	13-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Cadillac	XTS	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Avalanche	06	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9107	1070K	NO	Trigger required
Chevrolet	Avalanche	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Avalanche	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Avalanche	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Aveo	08-11		5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	OBDII required
Chevrolet	Blazer	19-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Blazer EV	24-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Bolt	17-18	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Bolt	19-21	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Bolt and EUV	22-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	BrightDrop 400 and 600	25		5003R (Program first)	3166	VS20	VS20	
Chevrolet	Camaro	10-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Camaro	16-19	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Camaro	20-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Camaro (clamp-in)	12-15	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Camaro (V8)	16-19	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Camaro (V8)	20-24	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Caprice	11-13	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Caprice	14-17	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	2030K	VS40	Trigger required
Chevrolet	Captiva	12-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	City Express	15-18	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Chevrolet	Cobalt (snap-in)	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Cobalt (clamp-in)	08-'09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Cobalt SS	10	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Colorado	07-12	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9131	1110K	NO	Trigger required
Chevrolet	Colorado	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Colorado	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Colorado	20	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Colorado	21-22	7006HPR		2346	VS20	VS20	Auto-relearn
Chevrolet	Colorado	23-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Corvette (C5)	97-00			8006	1077K	NO	Trigger required
Chevrolet	Corvette (C5)	01-04		5002' (Program first) or 5003M (Program first)	9117	1080K	NO	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Chevrolet	Corvette (C6)	05-09	7001HP	5002' (Program first) or 5003M (Program first)	9076	1070K	NO	Trigger required
Chevrolet	Corvette (C6)	10-13	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Corvette (C7)	14-19		5001 (Program first) or 5003M (Program first)	NEW	2030K	VS40	Auto-relearn
Chevrolet	Corvette (C8)	20-26		5003M (Program first)	8424	2030K	VS40	Auto-relearn
Chevrolet	Cruze	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Cruze Limited (315MHz)	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Cruze	16-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Cruze	19	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Equinox	07-09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Equinox	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Equinox	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Equinox	18-21	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Equinox	22-24	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	2346	VS20	VS20	Trigger required
Chevrolet	Equinox EV	24		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Equinox and EV	25-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Express Series	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Express 1500	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Express 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Express 2500/3500	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Express 2500/3500 (SRW)	17-26	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	HHR	08-10	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	HHR	08-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Impala	06-07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Impala	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Impala (new)	14-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Impala (new)	16-20	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Malibu (clamp-in)	08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Malibu	08-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Malibu (non-turbo)	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Malibu (turbo or Hybrid)	16-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Malibu	19-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Monte Carlo	05-07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Monte Carlo	07	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Orlando	12-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Silverado	18	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Silverado LD (old)	19	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Silverado 1500	19-21	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Silverado 1500 LTD	22	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Silverado 1500 (facelifted)	22-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Silverado HD	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 2500HD	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Silverado 2500HD	18-19	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Silverado HD (SRW)	20-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Silverado HD (SRW)	24-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Silverado 3500HD DRW (Front alloy wheel)	20-23		5001 (Program first) or 5003M (Program first)	7659	DA543E	DA543E	Trigger required
Chevrolet	Silverado 3500HD DRW (Front alloy wheel)	24-26		5003M (Program first)	7624	DA543E	DA543E	Trigger required
Chevrolet	Silverado 3500HD DRW (Front steel wheel)	20-23	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Silverado 3500HD DRW (Front steel wheel)	24-26		5003M (Program first)`	8424	2030K	VS40	Trigger required
Chevrolet	Silverado 3500HD DRW (Rear wheels)	20-23	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Silverado 3500HD DRW (Rear wheels)	24-26		5003M (Program first)`	8424	2030K	VS40	Trigger required
Chevrolet	Silverado Trailer TPMS	19-20	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	No tools needed
Chevrolet	Sonic	12-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Sonic	16-20	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Spark	13-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Spark	16-22	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	SS sedan	14	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	SS sedan	15-17	7001HP or 7007HP	5002' (Just relearn) or 5003M (Program first)	9158	2030K	VS40	Trigger required
Chevrolet	Suburban 1500	04		5002 (Program first) or 5003M (Program first)	9115	1070K	NO	Trigger required
Chevrolet	Suburban 1500	05-06	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9107	1070K	NO	Trigger required
Chevrolet	Suburban 1500	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Suburban 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Suburban 1500	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Suburban 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Suburban 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Suburban 2500	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Suburban	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Suburban	18-20	7006HPR or 7007HP	5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Suburban	21-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Tahoe	04		5002 (Program first) or 5003M (Program first)	9115	1070K	NO	Trigger required
Chevrolet	Tahoe	05-06	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9107	1070K	NO	Trigger required
Chevrolet	Tahoe	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Tahoe	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Tahoe	07-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Tahoe	18-20	7006HPR or 7007HP	5003R (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Tahoe	21-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Trailblazer	06-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
Chevrolet	Trailblazer	21-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Trailer TPMS	21-26	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	No tools needed
Chevrolet	Traverse	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Traverse	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Traverse	18-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Traverse	24-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Trax	15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Trax	16-22	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Trax	24-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Uplander	08-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Volt	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Volt	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Volt	17-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Volt (433MHz)	19	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Volt (315MHz)	19	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

4

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Chrysler	200	11-14	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Chrysler	200 sedan	15-16	7008HP		5775	VS90	VS90	Auto-relearn
Chrysler	200	17	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Chrysler	300M	02-04	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	Trigger required
Chrysler	300	05-07	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Chrysler	300	08	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	1050K	NO	Auto-relearn
Chrysler	300	09		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Chrysler	300	10-21		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Chrysler	300	22-23		5001 (Program first) or 5003M (Program first)	7472	1096	1096	Auto-relearn
Chrysler	300C SRT8	10-14		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Chrysler	Aspen	07-09	7001HP or 7007HP		1051'	9066K	9066K	Auto-relearn
Chrysler	Crossfire	04-08			9028	1080K	NO	Dealer OBD only
Chrysler	Grand Caravan (Canadian)	21-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Chrysler	Pacifica (433 MHz)	04	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	Trigger required
Chrysler	Pacifica (315 MHz)	04-05	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1052	1050K	NO	Auto-relearn
Chrysler	Pacifica	06-08	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Chrysler	Pacifica	17-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Chrysler	Prowler	01			8004	1077K	NO	Dealer OBD only
Chrysler	Prowler	02			9028	1080K	NO	Dealer OBD only
Chrysler	PT Cruiser	08-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1051	1050K	NO	Auto-relearn
Chrysler	Sebring	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Chrysler	Sebring	10	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Chrysler	Town and Country	02-03	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	Trigger required
Chrysler	Town and Country	04-05	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1052	1050K	NO	Auto-relearn
Chrysler	Town and Country	06-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1051	1050K	NO	Auto-relearn
Chrysler	Town and Country	08-10	7004 or 7008HP		1043	1050K	NO	Auto-relearn
Chrysler	Town and Country	10	7004 or 7008HP		1043	7000K	VS70	Auto-relearn
Chrysler	Town and Country	11-16		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Chrysler	Voyager	20-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Dodge	Avenger	08-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Avenger	11-14	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Dodge	Caliber	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Caliber	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Dodge	Caravan	04-05	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1052	1050K	NO	Auto-relearn
Dodge	Caravan	06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1051	1050K	NO	Auto-relearn
Dodge	Challenger SRT8	08-14		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Challenger	09		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Challenger	10-21		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Challenger	22-23		5001 (Program first) or 5003M (Program first)	7472	1096	1096	Auto-relearn
Dodge	Challenger 6.4L V8	15-21		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Challenger Hellcat / Demon	15-21		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger	06-07	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Charger	08	7004 or 7008HP		1043	1050K	NO	Auto-relearn
Dodge	Charger	09		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger SRT8	10-14		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger	10-21		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Charger	22-23		5001 (Program first) or 5003M (Program first)	7472	1096	1096	Auto-relearn
Dodge	Charger	24-26			NEW	1100K	VS40	Auto-learn
Dodge	Charger 6.4L V8	15-21		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger Hellcat	15-21		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Dakota	08-10	7001HP or 7007HP		9154	9066K	9066K	Auto-relearn
Dodge	Dakota	11	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	9308	VS950	VS950	Auto-relearn
Dodge	Dart	13-16	7008HP	5001 (Program first) or 5003M (Program first)	5775	VS90	VS90	Auto-relearn
Dodge	Durango	07-09	7001HP or 7007HP		1051'	9066K	9066K	Auto-relearn
Dodge	Durango	11-15		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Durango	16	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS90 or VS20	VS90 or VS20	Auto-relearn
Dodge	Durango	17-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Dodge	Durango SRT	18-26	7008HP	5001 (Program first) or 5003M (Program first)	2495	7020K	VS70	Auto-relearn
Dodge	Grand Caravan	02-03	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	Trigger required
Dodge	Grand Caravan	04-05	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1052	1050K	NO	Auto-relearn
Dodge	Grand Caravan	06-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1051	1050K	NO	Auto-relearn
Dodge	Grand Caravan	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Grand Caravan	10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	7000K	VS70	Auto-relearn
Dodge	Grand Caravan	11-20		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Hornet	23-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Dodge	Journey	09-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Journey	11-20		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Magnum	05-07	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Magnum	08	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Nitro	07-09	7001HP or 7007HP		1051'	9066K	9066K	Auto-relearn
Dodge	Nitro	10-11	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Dodge	Ram 1500	08			9154	9066K	9066K	Auto-relearn
Dodge	Ram 1500 (Siemens)	09	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Ram 1500 (Schrader)	09	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	9066K	9066K	Auto-relearn
Dodge	Ram 2500	08-09	7001HP		9154	9066K	9066K	Auto-relearn
Dodge	Ram	10-13		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Sprinter (SRW)	07-10		5002 (Program first) or 5003M (Program first)	1042	1098K	1098K	Trigger required'
Dodge	Viper	03-10			9028	1080K	NO	Dealer OBD only
Dodge	SRT Viper	13-17		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Ferrari	12Cilindri	25		5003M (Program first)	7420	1096	1096	No tools needed
Ferrari	296	22-24		5003M (Program first)	7420	1096	1096	No tools needed
Ferrari	F430	05-07		5003M (Program first)	9001	1090K	1092	No tools needed
Ferrari	F430 (Post July 2007)	07-09		5003M (Program first)	9011	1090K	1092	No tools needed
Ferrari	458	10-15		5003M (Program first)	9011	1096	1096	No tools needed
Ferrari	488	16-20		5003M (Program first)	9011	1096	1096	No tools needed
Ferrari	575M (433 MHz)	02-05		5003M (Program first)	9001	1090K	1092	No tools needed
Ferrari	575M (315 MHz)	02-05		5003M (Program first)	9004	1090K	1092	No tools needed
Ferrari	599	07-11		5003M (Program first)	9001	1090K	1092	No tools needed
Ferrari	612 Scaglinetta	05-10		5003M (Program first)	9001	1090K	1092	No tools needed
Ferrari	812	18-22		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Ferrari	California	09-10		5003M (Program first)	9011	1090K	1092	No tools needed
Ferrari	California	11-18		5003M (Program first)	9011	1096	1096	No tools needed
Ferrari	Enzo	03-05			9005	1090K	1092	
Ferrari	F8	20-22		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Ferrari	F12	13-17		5003M (Program first)	9011	1096	1096	No tools needed
Ferrari	FF	12-16		5003M (Program first)	9011	1096	1096	No tools needed
Ferrari	FXX	05-06			9005	1090K	1092	
Ferrari	GTC4 Lusso	17-20		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Ferrari	LaFerrari	14-15		5003M (Program first)	9011	1096	1096	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures-relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Ferrari	Portofino	19-22		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Ferrari	Purosangue	24		5003M (Program first)	7420	1096B	1096B'	No tools needed
Ferrari	Roma	21-22		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Ferrari	SF90	21-22		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Fiat	124 Spider Abarth	17-20	7001HP or 7007HP	5002 (Program first) or 5003R (Program first)	1056	7020K	VS70	Auto-relearn
Fiat	500	12-19		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Fiat	500L	14-20		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Fiat	500X	16-17	7008HP	5001 (Program first) or 5003R (Program first)	5775	VS90	VS90	Auto-relearn
Fiat	500X	18-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Fisker	Karma	10-12			NEW	VS1010	VS1010	Dealer OBD only
Ford	Bronco	21-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS950	VS950	Trigger required
Ford	Bronco	25-26		5003R (Program first)	9284	VS20	VS20	Auto-relearn
Ford	Bronco Sport	21-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	Bronco Sport	25-26		5003R (Program first)	9284	VS20	VS20	Auto-relearn
Ford	C-Max	13-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Crown Victoria	08-11	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	E Series	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048-HP	Banded	NO	Trigger required
Ford	E-250 / E-350 van	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048-HP	Banded	NO	Trigger required
Ford	E Series	10-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	E Series SRW	21-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	E Series SRW	25-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	E Series DRW (RV-prepped)	21-23	7003A or 7007HP	5002` (Program first) or 5003M (Program first)	9291	VS241	VS241	Trigger required
Ford	E Series DRW (RV-prepped)	25-26		5003M (Program first)`	9295	VS241	VS241	Trigger required
Ford	EcoSport	18-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	No tools needed
Ford	Edge	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Edge	11-14	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Edge	15-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Escape	05-08	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Escape	09-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Escape	20-25	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	E-Transit	22-25	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	E-Transit	26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	Expedition	03-04	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9096	1060K	NO	Trigger required
Ford	Expedition	05-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	Discontinu	1060K	NO	Trigger required
Ford	Expedition	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Expedition	11-17	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Expedition	18-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Expedition	23-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	Explorer	02-05	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9096	1060K	NO	Trigger required
Ford	Explorer Sport Trac	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Explorer	06-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Explorer	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Explorer	16-19	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Explorer	20-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	Explorer	25-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	F-150 Light Duty (6-Lug)	07-08	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	F-150 Heavy Duty (7-Lug)	07-08	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048-HP	Banded	NO	Trigger required
Ford	F-150	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	F-150	15-20	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	F-150	21-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS950	VS950	Trigger required
Ford	F-150	24-26		5003R (Program first)	9284	VS950	VS950	Trigger required
Ford	F-250 / F-350 SRW	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048-HP	Banded	NO	Trigger required
Ford	F-250 / F-350 SRW	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	F-250 / F-350 SRW	17-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	F-250 / F-350 (SRW)	23-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	F-350 DRW (clamp-in)	17-22	7003A or 7007HP	5002` (Program first) or 5003M (Program first)	9291	VS241	VS241	Trigger required
Ford	F-350 DRW (all steel wheels)	23-26		5003M (Program first)`	9295	VS241	VS241	Trigger required
Ford	F-350 DRW (front alloy wheel)	23-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	F-350 DRW (rear alloy wheel)	23-26		5003M (Program first)`	9295	VS241	VS241	Trigger required
Ford	F-250 / F-350 Trailer TPMS	17-20			9189	VS240MC	VS240MC	No tools needed
Ford	F450 (all wheels)	26			9364	DV416-WS	DV416-WS'	Trigger required
Ford	F550 / F600 (Alloy wheels)	23-26			9365	DV553C-WS	DV553C-WS	Trigger required
Ford	F550 / F600 (Steel wheels)	23-26			9364	DV416-WS	DV416-WS	Trigger required
Ford	Fiesta	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Flex	09-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Flex	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Focus	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Focus (non-RS)	10-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Focus RS (clamp-in)	16-18	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9315	VS240MC	VS240MC	Trigger required
Ford	Focus RS (snap-in)	16-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS20	VS20	Trigger required
Ford	Freestar	06-07	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Fusion	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Fusion	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Fusion	17-20	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	GT	17-22	7003A or 7007HP	5002' (Program first) or 5003M (Program first)	9291	VS240MC	VS240MC	Auto-relearn
Ford	Maverick	22-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Maverick	25-26		5003R (Program first)	9284	VS20	VS20	Auto-relearn
Ford	Mustang	07-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Mustang (snap-in)	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Mustang (clamp-in)	13-14	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9315	VS925C	VS925C	Trigger required
Ford	Mustang	15-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Mustang (clamp-in)	15-23	7003A or 7007HP	5002' (Program first) or 5003M (Program first)	9291	VS240MC	VS240MC	Auto-relearn
Ford	Mustang	24-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	Mustang (clamp-in)	24-26		5003M (Program first)	9295	VS240MC	VS240MC	Trigger required
Ford	Mustang Mach-E	21-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Mustang Mach-E	25		5003R (Program first)	9284	VS20	VS20	Auto-relearn
Ford	Police Interceptor sedan	13-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Police Interceptor Utility	13-15	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Police Interceptor Utility	16-25	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	Police Interceptor Utility	26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	Ranger	07-11	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Ranger	19-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	Ranger	25-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	Taurus	08-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Taurus	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Taurus X	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Ford	Trailer TPMS	17-24			9189	VS240MC	VS240MC	No tools needed
Ford	Trailer TPMS	25-26			NEW	DV416-WS	DV416-WS	No tools needed
Ford	Transit Connect	10-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Ford	Transit Connect	19-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	Transit (SRW)	15-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Ford	Transit (SRW)	20-25	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Trigger required
Ford	Transit (SRW)	26		5003R (Program first)	9284	VS20	VS20	Trigger required
Ford	Transit 350HD (DRW)	20-25	7003A or 7007HP	5002` (Program first) or 5003M (Program first)	9291	VS241	VS241	Trigger required
Ford	Transit (DRW)	26		5003M (Program first)	9295	VS241	VS241	Trigger required
Freightliner	Sprinter (SRW)	07-13		5002 (Program first) or 5003M (Program first)	1042	1098K	1098K	Trigger required'
Freightliner	Sprinter (SRW)	14-17		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
Freightliner	Sprinter (SRW)	18		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
Freightliner	Sprinter (SRW)	19-21		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
Genesis	G70	19-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	Auto-relearn
Genesis	G70	24-25	7008HP	5001 (Program first) or 5003M (Program first)	NEW	1100K	VS40	Auto-relearn
Genesis	G80	17-20	7008HP	5001 (Program first) or 5003M (Program first)	5510	7020K	VS70	Auto-relearn
Genesis	G80	21-25	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	Auto-relearn
Genesis	G90	17-22	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	Auto-relearn
Genesis	G90	23-25	7008HP	5001 (Program first) or 5003M (Program first)	NEW	1100K	VS40	Auto-relearn
Genesis	GV60	23-25	7008HP	5001 (Program first) or 5003M (Program first)	NEW	1100K	VS40	Auto-relearn
Genesis	GV70	22-26	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	Auto-relearn
Genesis	GV80	21-26	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	Auto-relearn
GMC	Acadia	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
GMC	Acadia	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Acadia	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Acadia Limited	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Acadia	17	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9773	VS20	VS20	Trigger required
GMC	Acadia	18-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
GMC	Acadia	24-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Canyon	07-12	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9131	1110K	NO	Trigger required
GMC	Canyon	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Canyon	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Canyon	20	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
GMC	Canyon	21-22	7006HPR		2346	VS20	VS20	Auto-relearn
GMC	Canyon	23-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Envoy	06-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
GMC	Hummer EV	22-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Savana	08-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
GMC	Savana	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Savana (SRW)	17-26	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Sierra 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	18	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra Limited	19	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra 1500	19-21	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra 1500 Limited	22	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra 1500 (facelifted)	22-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Sierra 2500/3500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Sierra 2500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 2500	18-19	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra HD (SRW)	20-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra HD (SRW)	24-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Sierra 3500HD DRW (Front alloy wheel)	20-23		5001 (Program first) or 5003M (Program first)	7659	DA543E	DA543E	Trigger required
GMC	Sierra 3500HD DRW (Front alloy wheel)	24-26		5003M (Program first)	7624	DA543E	DA543E	Trigger required
GMC	Sierra 3500HD DRW (Front steel wheel)	20-23	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Front steel wheel)	24-26		5003M (Program first)`	8424	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Rear wheels)	20-23	7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Rear wheels)	24-26		5003M (Program first)`	8424	2030K	VS40	Trigger required
GMC	Sierra Trailer TPMS	19-20	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	No tools needed
GMC	Terrain	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Terrain	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Terrain	18-21	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
GMC	Terrain	22-24	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	2346	VS20	VS20	Trigger required
GMC	Terrain	25-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Trailer TPMS	21-26	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	8463	2030K	VS40	No tools needed
GMC	Yukon 1500	04		5002 (Program first) or 5003M (Program first)	9115	1070K	NO	Trigger required
GMC	Yukon 1500	05-06	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9107	1070K	NO	Trigger required
GMC	Yukon	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
GMC	Yukon	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
GMC	Yukon 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	2020K	NO	Trigger required
GMC	Yukon 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	9158	1070K	NO	Trigger required
GMC	Yukon	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Yukon 2500	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
GMC	Yukon	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS20	VS20	Trigger required
GMC	Yukon	18-20	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	6164	VS20	VS20	Trigger required
GMC	Yukon	21-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Honda	Accord	08-12	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1208	1100K	NO	OBDII required
Honda	Civic	08-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Honda	CR-V	07-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1208	1100K	NO	OBDII required
Honda	CR-V	12-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	5511	7020K	VS70	OBDII required
Honda	CR-Z	11-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Honda	Crosstour	10-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	5511	7020K	VS70	OBDII required
Honda	Element	07-08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
Honda	Element	09-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Honda	Fit	08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1208	1100K	NO	OBDII required
Honda	Fit	09-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Honda	Insight	10-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Honda	Odyssey EX, EX-L, LX	07	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
Honda	Odyssey EX, EX-L, LX	08-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2045K or 2000K	None or 1096	OBDII required
Honda	Odyssey Touring	05-07	7002A or 7007HP	5003M (Program first)	1057	2000K	1096	Auto-relearn
Honda	Odyssey Touring	08-10	7002A or 7007HP	5003M (Program first)	1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Odyssey and Touring	11-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1212	2045K	NO	OBDII required
Honda	Odyssey	18-20			3751	7000K	VS70	Auto-relearn
Honda	Odyssey	21-26			5517	VS20	VS20	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Honda	Passport	19-21			3751	7000K	VS70	Auto-relearn
Honda	Passport	22-26			5517	VS20	VS20	Auto-relearn
Honda	Pilot (Steel Wheels)	05-08	7002A or 7007HP	5003M (Program first)	1059	2000K	1097	Auto-relearn
Honda	Pilot (Alloy Wheels)	05-08	7002A or 7007HP	5003M (Program first)	1057	2000K	1096	Auto-relearn
Honda	Pilot (Alloy Wheels)	09-15	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Honda	Pilot (Steel Wheels)	09-15	7002A or 7007HP		1219	1100K	NO	Auto-relearn
Honda	Pilot	16-22			3751	7000K	VS70	Auto-relearn
Honda	Pilot	23-26			5517	VS20	VS20	Auto-relearn
Honda	Prologue	24-26		5003R (Program first)	3166	VS20	VS20	Auto-relearn
Honda	Ridgeline (Steel Wheels)	06-08	7002A or 7007HP	5003M (Program first)	1059	2000K	1097	Auto-relearn
Honda	Ridgeline (Alloy Wheels)	06-08	7002A or 7007HP	5003M (Program first)	1057	2000K	1096	Auto-relearn
Honda	Ridgeline	09-14	7002A or 7007HP	5003M (Program first)	1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Ridgeline	17-20			3751	7000K	VS70	Auto-relearn
Honda	Ridgeline	21-26			5517	VS20	VS20	Auto-relearn
Honda	S2000	08-09	7002A or 7007HP	5002' (Program first) or 5003M (Program first)	1208	1100K	NO	OBDII required
Hummer	H2	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Hummer	H3	06-10	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9131	1110K	NO	Trigger required
Hummer	H3T	09-10	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9131	1110K	NO	Trigger required
Hyundai	Accent	08-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
Hyundai	Accent	12-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
Hyundai	Accent	14	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Accent	15-22	7008HP	5001 (Program first) or 5003M (Program first)	5510	7020K	VS70	OBDII required
Hyundai	Azera	07-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
Hyundai	Azera (315MHz)	12-14		5002 (Program first) or 5003M (Program first)	1233	2040K	VS965	OBDII required
Hyundai	Azera (433MHz)	14-17		5001 (Program first) or 5003M (Program first)	NEW	2040K	VS965	OBDII required
Hyundai	Elantra	08-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
Hyundai	Elantra	11-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1222	2040K	VS965	OBDII required
Hyundai	Elantra	14-16	7007HP	5002 (Program first) or 5003M (Program first)	3205	2040K	VS965	OBDII required
Hyundai	Elantra	17-20	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Elantra and N-Line	21-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Elantra N	22-23	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Elantra N	24-25	7005HPR or 7008HP	5001 (Program first) or 5003M (Program first)	NEW	1100K	VS40	OBDII required
Hyundai	Elantra Touring (hatchback)	09-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	1050K or 7020K	None or VS70	Auto-relearn
Hyundai	Elantra GT	13-17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Elantra GT	18-20	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Entourage	07-08		5002 (Program first) or 5003M (Program first)	1028	2000K	1096	OBDII required
Hyundai	Equus	11-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
Hyundai	Equus	14-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Genesis Sedan	09-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
Hyundai	Genesis Sedan	15-16	7008HP	5001 (Program first) or 5003M (Program first)	5510	7020K	VS70	OBDII required
Hyundai	Genesis Coupe	10-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
Hyundai	Genesis Coupe	13-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Ioniq	17-22	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Ioniq 5	22-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Ioniq 5 N	25	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Ioniq 6 (Conti)	23	7008HP	5001 (Program first) or 5003M (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Ioniq 6 (Schrader)	23-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Ioniq 9	26		5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Kona	18-23	7008HP	5001 (Program first) or 5003R (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Kona	24-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Nexo	19-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Palisade	20-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Santa Cruz	22-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Santa Fe	07-08		5002 (Program first) or 5003M (Program first)	1028	2000K	1096	OBDII required
Hyundai	Santa Fe	09	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
Hyundai	Santa Fe	10-12	7002A or 7007HP	5002 (Program first) or 5003R (Program first)	1068	VS1010	VS1010	OBDII required
Hyundai	Santa Fe	13-18	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Santa Fe XL	19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Santa Fe Sport	18	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Santa Fe (non-XL)	19-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Sonata	07	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
Hyundai	Sonata GLS/Limited	08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
Hyundai	Sonata SE	08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
Hyundai	Sonata	09-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
Hyundai	Sonata	11-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
Hyundai	Sonata	13-14	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Sonata Hybrid	15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Sonata (non-hybrid)	15	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Sonata	16-19	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Sonata	20-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Sonata N-Line	21-25	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Tiburon	07-08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
Hyundai	Tucson	06-09	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
Hyundai	Tucson	10-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
Hyundai	Tucson	14-15	7007HP	5002 (Program first) or 5003M (Program first)	2510	2040K	VS965	OBDII required
Hyundai	Tucson	16-21	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Tucson	22-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Veloster	12-17	7007HP	5002 (Program first) or 5003M (Program first)	9505	VS950	VS950	OBDII required
Hyundai	Veloster	19-22	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Venue	20-25	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Veracruz	07-08		5002 (Program first) or 5003M (Program first)	1028	2000K	1096	OBDII required
Hyundai	Veracruz	09-12	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
INEOS	Grenadier	24	7008HP	5001 (Program first) or 5003M (Program first)	5559	7020K	VS70	Dealer OBD only
Infiniti	EX	08-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Infiniti	EX (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	FX	03-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Infiniti	FX	08	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Infiniti	FX	09-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Infiniti	FX (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	G35	04-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Infiniti	G35 Coupe (Post Aug. 2006)	07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Infiniti	G35 Sedan	07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Infiniti	G	08-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Infiniti	G (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	JX	13		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Infiniti	M	03-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Infiniti	M	08-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

8

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Infiniti	M (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	Q40	15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	Q45	03-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Infiniti	Q50	14-15		5002 (Program first) or 5003M (Program first)	5558	7020K	VS70	OBDII required
Infiniti	Q50	16-24		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Infiniti	Q60	14-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	Q60	17-22		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Infiniti	Q70	14-19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX30	17-19		5001 (Just relearn) or 5003M (Program first)	9214	1100K	VS40	No tools needed
Infiniti	QX50	14-17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX50	19-22	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Infiniti	QX50	22-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Infiniti	QX55	22	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Infiniti	QX55	23-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Infiniti	QX56	04-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Infiniti	QX56	08-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Infiniti	QX56 (Post March 2010)	10	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX56	11-13	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX60	14-20		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Infiniti	QX60 (snap-in)	20		5001 (Program first) or 5003R (Program first)	5564	VS20	VS20	OBDII required
Infiniti	QX60	22-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Infiniti	QX70	14-17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX80	14-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX80	17	7008HP	5001 (Program first) or 5003M (Program first)	1382	1100K	NO	OBDII required
Infiniti	QX80	18-22	7006HPR	5002 (Program first) or 5003M (Program first)	1375	1100K	NO	OBDII required
Infiniti	QX80	23-24	7006HPR	5002 (Program first) or 5003M (Program first)	1375	1100K	VS312	OBDII required
Infiniti	QX80	25	7006HPR	5002 (Program first) or 5003R (Program first)	4761	VS15	VS15	OBDII required
Isuzu	Ascender	06-08	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
Isuzu	I-series pickup	07-08	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	9131	1110K	NO	Trigger required
Isuzu	Rodeo	04			9028	1080K	NO	Dealer OBD only
Jaguar	E-Pace	18-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	E-Pace	22-24	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	F-Pace	17-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	F-Pace	22-25	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	F-Type (315MHz)	14-15		5002 (Program first) or 5003M (Program first)	1045	7020K	VS70	Auto-relearn
Jaguar	F-Type (433MHz Export)	14			1046	1050K	NO	Auto-relearn
Jaguar	F-Type (433MHz)	15-24	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	I-Pace (clamp-in)	19-22	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	I-Pace (snap-in)	22-24	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	X-Type (315MHz)	08		5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	X-Type (433MHz Export)	08			1046	1050K	NO	Auto-relearn
Jaguar	XE	17-20	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XF (315MHz)	09-16		5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XF (433MHz Export)	09-15			1046	1050K	NO	Auto-relearn
Jaguar	XF (433MHz)	16-24	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XJ (315MHz)	06-09		5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	10-11		5002 (Program first) or 5003M (Program first)	1045	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz Export)	06-11			1046	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	12-16		5002 (Program first) or 5003M (Program first)	1045	1050K or 7020K	None or VS70	Auto-relearn
Jaguar	XJ (433MHz Export)	12-14			1046	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz)	15-19	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XK (315MHz)	07-15		5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XK (433MHz Export)	07-15			1046	1050K	NO	Auto-relearn
Jeep	Cherokee	14-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6815	VS65	VS65	Auto-relearn
Jeep	Cherokee	19-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6896	VS65	VS65	Auto-relearn
Jeep	Cherokee	26			NEW	VS20	VS20	Auto-relearn
Jeep	Commander	06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Commander	07	7001HP or 7007HP		1051'	9066K	9066K	Auto-relearn
Jeep	Commander	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Compass	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Compass	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Jeep	Compass (315MHz)	13-17	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz Export)	13-14		5001 (Program first) or 5003R (Program first)	9481	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz)	17-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Gladiator	20-21		5001 (Program first) or 5003R (Program first)	4665	VS950	VS950	Auto-relearn
Jeep	Gladiator (built on or after 6/7/2021)	21-25		5003R (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee	02-04	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	Trigger required
Jeep	Grand Cherokee	05-06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Grand Cherokee	07	7001HP or 7007HP		1051'	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	11-15		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Grand Cherokee	16	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS90	VS90	Auto-relearn
Jeep	Grand Cherokee (non-L)	17-21	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee (WK)	22	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee L	21		5003R (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee (New) and L	22-24		5003R (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee and L	24-25			NEW	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee SRT8	12-15		5001 (Just relearn) or 5003M (Program first)	9214	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee SRT	16-21	7008HP	5001 (Program first) or 5003M (Program first)	2495	7020K	VS70	Auto-relearn
Jeep	Grand Wagoneer	22-23		5003R (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Wagoneer	24-25			NEW	VS20	VS20	Auto-relearn
Jeep	Liberty	04	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	Trigger required
Jeep	Liberty	05-06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Liberty	07-10	7001HP or 7007HP		1051'	9066K	9066K	Auto-relearn
Jeep	Liberty	10-12	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Liberty (433MHz Export)	07-09	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Liberty (433MHz Export)	10-12		5001 (Program first) or 5003R (Program first)	9481	VS950	VS950	Auto-relearn
Jeep	Patriot	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Patriot	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Jeep	Patriot	13-17	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Patriot (433MHz Export)	12-14		5001 (Program first) or 5003R (Program first)	9481	VS950	VS950	Auto-relearn
Jeep	Renegade	15-16	7008HP	5001 (Program first) or 5003R (Program first)	5775	VS90	VS90	Auto-relearn
Jeep	Renegade	17-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Wagoneer	22-24		5003R (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Wagoneer	24-25			NEW	VS20	VS20	Auto-relearn
Jeep	Wagoneer	25-26			NEW	VS20	VS20	Auto-relearn
Jeep	Wrangler	07-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1051'	9066K	9066K	Auto-relearn
Jeep	Wrangler (433MHz Export)	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	9066K	9066K	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Jeep	Wrangler	10-12	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	9308	VS950	VS950	Auto-relearn
Jeep	Wrangler (433MHz Export)	10-12		5001 (Program first) or 5003R (Program first)	9481	VS950	VS950	Auto-relearn
Jeep	Wrangler (JK)	13-18		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler (JL)	18-20		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler	21		5001 (Program first) or 5003R (Program first)	4665	VS950	VS950	Auto-relearn
Jeep	Wrangler (built on or after 6/7/2021)	21-25		5003R (Program first)	3996	VS20	VS20	Auto-relearn
KIA	Amanti	07-08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
KIA	Amanti	09	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
KIA	Borrego	09-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
KIA	Cadenza	14-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
KIA	Cadenza	17-20	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	Carnival	22-24	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Carnival (non-hybrid)	25-26	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Carnival Hybrid	25-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	EV6 (snap-in)	22-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	EV6 (snap-in)	25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	EV6 GT (clamp-in)	23-24	7008HP	5001 (Program first) or 5003M (Program first)	NEW	1100K	VS40	OBDII required
KIA	EV9	24-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Forte	10-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
KIA	Forte	14-15	7007HP	5002 (Program first) or 5003M (Program first)	2510	2040K	VS965	OBDII required
KIA	Forte	16-18	7007HP	5002 (Program first) or 5003M (Program first)	3205	2040K	VS965	OBDII required
KIA	Forte	19-24		5001 (Program first) or 5003M (Program first)	NEW	1100K	NO	OBDII required
KIA	K4	25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	K5 (snap-in)	21-26	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	K5 GT (clamp-in)	21-26	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	K900	15-17			NEW	VS950	VS950	OBDII required
KIA	K900	19-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
KIA	Magentis	08-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
KIA	Niro	17-22	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	Niro	23-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Optima	06-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
KIA	Optima	11-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
KIA	Optima	14-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
KIA	Optima Hybrid	16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
KIA	Optima non-hybrid	16	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	Optima	17-20	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	Rio	08-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
KIA	Rio	12-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1222	2040K	VS965	OBDII required
KIA	Rio	18-23	7008HP	5001 (Program first) or 5003M (Program first)	5510	7020K	VS70	OBDII required
KIA	Rondo	07-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
KIA	Sedona	06-08		5002 (Program first) or 5003M (Program first)	1028	2000K	1096	OBDII required
KIA	Sedona	09-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1068	2000K	1096	OBDII required
KIA	Sedona	15-18	7008HP	5001 (Program first) or 5003R (Program first)	3210	VS20	VS20	OBDII required
KIA	Sedona	19-21	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
KIA	Seltos	21-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Sorento (with tire display)	07-08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
KIA	Sorento (without tire display)	08-09	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
KIA	Sorento	11-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
KIA	Sorento	14-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5508	7020K	VS70	OBDII required
KIA	Sorento	16-17	7008HP	5001 (Program first) or 5003M (Program first)	5510	7020K	VS70	OBDII required
KIA	Sorento	18-20	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	Sorento	21-25	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Soul	10-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5507	7020K	VS70	OBDII required
KIA	Soul	14-19	7008HP	5001 (Program first) or 5003R (Program first)	3210	VS20	VS20	OBDII required
KIA	Soul	20-25	7008HP	5001 (Program first) or 5003R (Program first)	5523	7020K	VS70	OBDII required
KIA	Spectra	07-09	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
KIA	Sportage	06-08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1058	2000K	1096	OBDII required
KIA	Sportage	09-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1029	2040K	NO	OBDII required
KIA	Sportage	14-16	7007HP	5002 (Program first) or 5003M (Program first)	2510	2040K	VS965	OBDII required
KIA	Sportage	17-22	7008HP	5001 (Program first) or 5003M (Program first)	5523	7020K	VS70	OBDII required
KIA	Sportage	23-26	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Stinger	18-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
KIA	Telluride	20-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	9237	VS20	VS20	OBDII required
Lamborghini	Aventador	12-22		5003M (Program first)	9011	1096	1096	No tools needed
Lamborghini	Gallardo	08-14		5003M (Program first)	9011	1096	1096	No tools needed
Lamborghini	Huracan	15-24		5003M (Program first)	9011	1096	1096	No tools needed
Lamborghini	Murcielago	08-10		5003M (Program first)	9011	1096	1096	No tools needed
Lamborghini	Urus	19-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Land Rover	Defender	20-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Defender	21-25	7008HP	5001 (Program first) or 5003M (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	Discovery	17-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Discovery	21-25	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	Discovery Sport	15-18	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Discovery Sport	19-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Discovery Sport	21-25	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	LR2	08-10		5002 (Program first) or 5003M (Program first)	1045	1050K	NO	Auto-relearn
Land Rover	LR2	10-15		5002 (Program first) or 5003M (Program first)	1045	7020K	VS70	Auto-relearn
Land Rover	LR3	06-09	7001HP	5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Land Rover	LR4 (315MHz)	10-14		5002 (Program first) or 5003M (Program first)	1045**	7020K	VS70	Auto-relearn
Land Rover	LR4 (433MHz)	13-16	7008HP	5001 (Program first) or 5003M (Program first)	5276**	7020K	VS70	Auto-relearn
Land Rover	Range Rover	03-05			9003	1090K	1092	No tools needed
Land Rover	Range Rover	06-09	7001HP	5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Land Rover	Range Rover (315MHz)	10-14		5002 (Program first) or 5003M (Program first)	1045**	1050K or 7020K	None or VS70	Auto-relearn
Land Rover	Range Rover (433MHz)	14-15	7008HP	5001 (Program first) or 5003M (Program first)	5276**	7020K	VS70	Auto-relearn
Land Rover	Range Rover	16-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover (4th Gen)	21-22	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	Range Rover (5th Gen)	22-25	7008HP	5003R (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	Range Rover Evoque (315MHz)	12-14		5002 (Program first) or 5003M (Program first)	1045**	7020K	VS70	Auto-relearn
Land Rover	Range Rover Evoque (433MHz)	14-15	7008HP	5001 (Program first) or 5003M (Program first)	5276**	7020K	VS70	Auto-relearn
Land Rover	Range Rover Evoque	16-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover Evoque	21-25	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	Range Rover Sport	06-09	7001HP	5002 (Program first) or 5003M (Program first)	1055	1050K	NO	Auto-relearn
Land Rover	Range Rover Sport (315MHz)	10-14		5002 (Program first) or 5003M (Program first)	1045**	1050K or 7020K	None or VS70	Auto-relearn
Land Rover	Range Rover Sport (433MHz)	14-18	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover Sport	19-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover Sport	21-22	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Land Rover	Range Rover Sport	23-25	7008HP	5003R (Program first)	5077	VS20	VS20	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Land Rover	Range Rover Velar	18-21	7008HP	5001 (Program first) or 5003M (Program first)	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover Velar	21-25	7008HP	5001 (Program first) or 5003R (Program first)	5077	VS20	VS20	Auto-relearn
Lexus	CT200h	11-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	ES	07-12	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	ES	13-18			1218	1100K	NO	OBDII required
Lexus	ES	19	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Lexus	ES	20-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	GS	06-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	GS	13-20			1218	1100K	NO	OBDII required
Lexus	GX	03-06	7002A* or 7007HP*	5002 (Program first) or 5003M (Program first)	1204 (OE),	1110K (OE), 2	None (OE), 1096	OBDII required
Lexus	GX	07-09	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	GX	10-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	GX	18-19			1218	1100K	NO	OBDII required
Lexus	GX	20-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Lexus	GX	22-23	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	GX	24-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Lexus	HS250h	10-12	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	IS	06-13	7002A* or 7007HP*	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	IS C 2dr.	14-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	IS-F (V8 only)	14	7002A or 7007HP	5002' (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	IS250 / IS350 4dr.	14-15			1218	1100K	NO	OBDII required
Lexus	IS	16-20			1218	1100K	NO	OBDII required
Lexus	IS	21-22	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	IS	23-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	LC 500	18-19	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Lexus	LC	20-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Lexus	LC	22-23	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	LC	24-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	LFA	11-13	7002A or 7007HP	5002' (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	LS	07-12	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	LS	13-17			1218	1100K	NO	OBDII required
Lexus	LS	18-20	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Lexus	LS	21-22	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	LS	23-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	LX	06-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	LX	16-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Lexus	LX	22-23	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	LX	24-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	NX	15-21			1218	1100K	NO	OBDII required
Lexus	NX (433MHz)	22-25		5003M (Program first)	2433	1100K	VS312	Trigger required
Lexus	NX (315MHz Used in N.A.)	22-23	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	NX (315MHz)	24-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	RC and RC-F	15-20			1218	1100K	NO	OBDII required
Lexus	RC-F (8cyl)	21-22			1218	1100K	NO	OBDII required
Lexus	RC (4 and 6cyl)	21-22	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	RC	23-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	RX	07-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	RX	16-19	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Lexus	RX	20-22	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	OBDII required
Lexus	RX (315MHz)	23-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	RX (433MHz)	24-25		5003M (Program first)	2433	1100K	VS312	Trigger required
Lexus	RZ	23-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	SC430**	02-06			1217-WH 1217-BL 1217-RD 1217-YL**	1120K (1G), 1100K (2G)	NO	Dealer OBD only
Lexus	SC430	07-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Lexus	TX	24-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230-BLK	1100BLK	VS312B	Trigger required
Lexus	UX	19-20	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Lexus	UX	21-24	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Lexus	UX	25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required

* Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).
** Note: Dealer tool is required for the relearn.

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Lincoln	Aviator	03-05	7004 or 7008HP	5001 (Program first) 5003M (Program first)	9096	1060K	NO	Trigger required
Lincoln	Aviator	20-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	Aviator	25-26		5003R (Program first)	9284	VS20	VS20	Auto-relearn
Lincoln	Continental	17-21	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	Corsair	20-26	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	Mark LT	07-08	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	MKC	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Lincoln	MKC	18-19	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	MKS	09-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	MKS	11-16	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Lincoln	MKT	10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	MKT	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Lincoln	MKX	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	MKX	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Lincoln	MKX	16-18	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	MKZ	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	MKZ	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Lincoln	MKZ	17-20	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	Nautilus	19-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	Nautilus	24-26		5003R (Program first)	9284	VS20	VS20	Auto-relearn
Lincoln	Navigator	03-04	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9096	1060K	NO	Trigger required
Lincoln	Navigator	05-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	Discontinu	1060K	NO	Trigger required
Lincoln	Navigator	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	Navigator	11-17	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Lincoln	Navigator	18-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9280	VS20	VS20	Auto-relearn
Lincoln	Navigator	23-26		5003R (Program first)	9284	VS20	VS20	Trigger required
Lincoln	Town Car	08-11	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Lincoln	Trailer TPMS	22-24			9189	VS240MC	VS240MC	No tools needed
Lincoln	Trailer TPMS	25-26			NEW	DV416-WS	DV416-WS	No tools needed
Lotus	Elise	08-11		5001 (Program first) or 5003M (Program first)	9159	2010K	NO	Auto-relearn
Lotus	Evora	10-17		5001 (Program first) or 5003M (Program first)	9159	2010K	NO	Auto-relearn
Lotus	Evora	18-21			NEW	1096	1096	
Lotus	Exige	08-11		5001 (Program first) or 5003M (Program first)	9159	2010K	NO	Auto-relearn
Lucid Motors	Air	22-25		5001 (Program first) or 5003M (Program first)	2168	7020K	VS70B	Auto-relearn
Lucid Motors	Gravity	25		5001 (Program first) or 5003M (Program first)	2168	7020K	VS70B	Auto-relearn
Maserati	Coupe/Spyder	05-06		5003M (Program first)	9001	1090K	1092 or 1094	

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Maserati	Ghibli	14-21		5001 (Program first) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
Maserati	Ghibli	22-24	7008HP	5001 (Program first) or 5003M (Program first)	2495	7020K	VS70	Auto-relearn
Maserati	GranTurismo	08-09		5003M (Program first)	9001	1090K	1092	No tools needed
Maserati	GranTurismo	10-19		5003M (Program first)	9011	1096	1096	No tools needed
Maserati	GranTurismo	24			NEW	7020K	VS70	Auto-relearn
Maserati	Grecale	23-24			NEW	7020K	VS70	Auto-relearn
Maserati	Levante	17-21		5001 (Just relearn) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
Maserati	Levante	22-24	7008HP	5001 (Program first) or 5003M (Program first)	2495	7020K	VS70	Auto-relearn
Maserati	MC20	22			NEW	7020K	VS70	Auto-relearn
Maserati	Quattroporte	05-10		5003M (Program first)	9001	1090K	1092	No tools needed
Maserati	Quattroporte	11-13		5003M (Program first)	9011	1096	1096	No tools needed
Maserati	Quattroporte	14-21		5001 (Program first) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
Maserati	Quattroporte	22-24	7008HP	5001 (Program first) or 5003M (Program first)	2495	7020K	VS70	Auto-relearn
Mazda	B-Series	07-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Auto-relearn
Mazda	CX-3	19-20	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	CX-3	21-22	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	CX-30	20-26	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	CX-5	17-20	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	CX-5	21-25	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20'	Auto-relearn
Mazda	CX-50	23-26	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	CX-7	07-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	CX-7	10-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	CX-70	25-26	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	CX-9	07-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	CX-9	10-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	CX-9	18-19	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	CX-9	20-23	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	CX-90	24-26	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	2	11-14	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	3	04	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1130K	NO	Auto-relearn
Mazda	3	05-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	3	10-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	3	19-26	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	5	06-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	5	10-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	6	08-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	6	10-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	6	18-20	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	6	21	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	MX-30	22-23	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	MX-5 Miata	06-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	MX-5 Miata	10-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	MX-5 Miata	18-20	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	MX-5 Miata	21-26	7006HPR	5002 (Program first) or 5003R (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	RX-8	04	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1130K	NO	Auto-relearn
Mazda	RX-8	05-10	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	1050K	NO	Auto-relearn
Mazda	RX-8	10-11	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	Tribute	05-08	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Auto-relearn
Mazda	Tribute	09-11	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Auto-relearn
McLaren	MP4-12c	12-14		5003M (Program first)	9011	1096	1096	Auto-relearn
McLaren	P1	14-15		5003M (Program first)	9011	1096	1096	Auto-relearn
McLaren	570GT	17-18		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
McLaren	570S	16		5003M (Program first)	9011	1096	1096	Auto-relearn
McLaren	570S	19-20		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
McLaren	650S	15-16		5003M (Program first)	9011	1096	1096	Auto-relearn
McLaren	675LT	16		5003M (Program first)	9011	1096	1096	Auto-relearn
McLaren	720S	18-20		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
M-Benz	A-Class	19-22		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	AMG GT 2-dr	16-21		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	AMG GT 2-dr	24-26		5001 (Program first) or 5003M (Program first)`	9077	2030K	VS40	No tools needed
M-Benz	AMG GT 4-dr	19-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	B-Class	14-17		5001 (Program first) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	C-Class	08-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	C-Class	15-21		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	C-Class coupe	22-23		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	C-Class sedan	22-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	CL-Class	01-06		5003M (Program first)	9004	1090K	1094	No tools needed
M-Benz	CL-Class	07-09	7003A or 7007HP		1054	1040K	1040K	Trigger required'
M-Benz	CL-Class	10-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	CLA-Class	14-19		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	CLA-Class	20-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	CLE-Class	24-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	CLK-Class	08-09		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	CLS-Class	06-11	7003A or 7007HP		1054	1040K	1040K	Trigger required'
M-Benz	CLS-Class	12-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	CLS-Class	15-18		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	CLS-Class	19-23		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	E-Class	03-06		5003M (Program first)	9004	1090K	1094	No tools needed
M-Benz	E-Class	07-09	7003A or 7007HP		1054	1040K	1040K	Trigger required'
M-Benz	E-Class	10-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	E-Class	15-16		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	E-Class 2dr.	17		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	E-Class sedan and wagon	17		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	E-Class	18-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	EQB	22-25		5001 (Program first) or 5003M (Program first)	9077'	1096	1096	No tools needed
M-Benz	EQE sedan	23-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	EQE SUV	23-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	EQS sedan	22-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	EQS SUV	23-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	eSprinter	24-26		5001 (Program first) or 5003M (Program first)	9077'	1096	1096	No tools needed
M-Benz	G-Class	07-15		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	G-Class	16-18		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	G-Class	19-24		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	G-Class	25-26		5001 (Program first) or 5003M (Program first)	9077	1096'	1096'	No tools needed
M-Benz	GL-Class	07-09		5001 (Program first) or 5003M (Program first)	1049	1040K	1040K	No tools needed
M-Benz	GL-Class	10-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	GL-Class	15-16		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	GLA-Class	15-20		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	GLA-Class	21-26		5001 (Program first) or 5003M (Program first)	9077'	1096	1096	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

12

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
M-Benz	GLB-Class	20-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	GLC-Class (X253)	16-23		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	GLC-Class	23-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	GLE-Class	16-19		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	GLE-Class	20-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	GLK-Class	10-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	GLK-Class	15		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	GLS-Class	17-19		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	GLS-Class	20-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	Maybach S-Class	16-20		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	Maybach S-Class	21-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	Maybach SL-Class	26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	Maybach GLS-Class	21-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	Metris	16-23		5001 (Just relearn) or 5003R (Program first)	9398	VS20	VS20	No tools needed
M-Benz	ML-Class	07-09		5001 (Program first) or 5003M (Program first)	1049	1040K	1040K	No tools needed
M-Benz	ML-Class	10-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	ML-Class	15		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	R-Class	07-09		5001 (Program first) or 5003M (Program first)	1049	1040K	1040K	No tools needed
M-Benz	R-Class	10-12		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	S-Class	01-06		5003M (Program first)	9004	1090K	1094	No tools needed
M-Benz	S-Class	07-09	7003A or 7007HP		1054	1040K	1040K	Trigger required'
M-Benz	S-Class	10-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	S-Class	15-20		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	S-Class 2dr.	21		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	S-Class sedan	21-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	SL-Class	03-05		5003M (Program first)	9004	1090K	1094	No tools needed
M-Benz	SL-Class	06-12	7003A or 7007HP		1054	1040K	1040K	Trigger required'
M-Benz	SL-Class	13-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	SL-Class	15-20		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	SL-Class	22-26		5001 (Program first) or 5003M (Program first)	9077	2030K	VS40	No tools needed
M-Benz	SLC-Class	17-20		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	SLK-Class	08-14		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	SLK-Class	15-16		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	SLR McLaren (315 MHz)	05-07		5003M (Program first)	9004	1090K	1094	No tools needed
M-Benz	SLR McLaren (433 MHz)	05-07		5003M (Program first)	9001	1090K	1094	No tools needed
M-Benz	SLR McLaren (315 MHz)	08-09	7003A or 7007HP		1054	1040K	1040K	Trigger required'
M-Benz	SLR McLaren (433 MHz)	08-09		5001 (Program first) or 5003M (Program first)	1049	1040K	1040K	No tools needed
M-Benz	SLS AMG	11-15		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	Sprinter SRW (315MHz)	07-13		5002 (Program first) or 5003M (Program first)	1042	1098K	1098K	Trigger required'
M-Benz	Sprinter SRW (433MHz)	13-17		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
M-Benz	Sprinter (SRW)	18		5001 (Just relearn) or 5003M (Program first)	9214	2030K	VS40	No tools needed
M-Benz	Sprinter (SRW)	19-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	No tools needed
M-Benz	Sprinter (DRW)	25-26			NEW	VS520	VS520	
Mercury	Grand Marquis	08-11	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Mercury	Mariner	05-08	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Mercury	Mariner	09-11	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Mercury	Milan	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Mercury	Milan	10-11	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required
Mercury	Monterey	06-07	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Mercury	Mountaineer	03-05	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9096	1060K	NO	Trigger required
Mercury	Mountaineer	06-10	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Mercury	Sable	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	1048	Banded	NO	Trigger required
Mini	All models	07-09		5003M (Program first)	1027	1090K	1091-1095	No tools needed
Mini	All models	10-13		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Cabrio	14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Cabrio (Post March 2014)	14-15		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Mini	Convertible	16-24	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
Mini	Convertible	25		5001 (Program first) or 5003M' (Program first)	9077	1096	1096'	No tools needed
Mini	Clubman	14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Clubman (Post July 2014)	14-24	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
Mini	Countryman	14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Countryman (Post March 2014)	14-16		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Mini	Countryman	17-24	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
Mini	Countryman	25-26		5001 (Program first) or 5003M' (Program first)	9077	1096	1096'	No tools needed
Mini	Coupe	14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Coupe (Post March 2014)	14-15		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Mini	Hatchback	14-24	7008HP	5001 (Program first) or 5003M (Program first)	5256	7020K	VS70	No tools needed
Mini	Hatchback	25		5001 (Program first) or 5003M' (Program first)	9077	1096	1096'	No tools needed
Mini	Paceman	14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Paceman (Post March 2014)	14-16		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Mini	Roadster	14		5001 (Program first) or 5003M (Program first)	9012	1096	1096	No tools needed
Mini	Roadster (Post March 2014)	14-15		5001 (Program first) or 5003M (Program first)	9017	1096	1096	No tools needed
Mitsubishi	Eclipse (w/ Alloy wheels)	08-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9034	1080K	NO	OBDII required
Mitsubishi	Eclipse (w/ Steel wheels)	08-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Mitsubishi	Eclipse Cross**	18-22	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	Eclipse Cross	23-25	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Mitsubishi	Endeavor	04-06	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	OBDII required
Mitsubishi	Endeavor (w/ Steel wheels)	07-08	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Mitsubishi	Endeavor (w/ Alloy wheels)	07-11	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9034	1080K	NO	OBDII required
Mitsubishi	Galant	06	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	9028	1080K	NO	OBDII required
Mitsubishi	Galant (w/ Alloy wheels)	07-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9034	1080K	NO	OBDII required
Mitsubishi	Galant (w/ Steel wheels)	07-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Mitsubishi	i-MiEV**	12-17	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	7020K	VS70	OBDII required
Mitsubishi	Lancer**	08-10	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	1050K	NO	OBDII required
Mitsubishi	Lancer**	10-17	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	7020K	VS70	OBDII required
Mitsubishi	Mirage (clamp-in)**	14-15	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	7020K	VS70	OBDII required
Mitsubishi	Mirage (snap-in)**	14-23	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	Mirage	24	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
Mitsubishi	Montero (w/ Alloy wheels)	03-06			9034	1080K	NO	Dealer OBD only
Mitsubishi	Montero (w/ Steel wheels)	03-06			9069	1130K	NO	Dealer OBD only
Mitsubishi	Outlander**	07-10	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	1050K	NO	OBDII required
Mitsubishi	Outlander and Sport**	10-17	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	7020K	VS70	OBDII required
Mitsubishi	Outlander Sport**	13	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	Outlander and Sport (clamp-in)**	18	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	7020K	VS70	OBDII required
Mitsubishi	Outlander and Sport (snap-in)	18-20	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	Outlander	21	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	Outlander PHEV	22	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	Outlander Sport	21-25	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

13

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Mitsubishi	Outlander	22-25	7006HPR	5002 (Program first) or 5003R (Program first)	4762	VS20	VS20	Auto-relearn
Mitsubishi	Raider	08-09	7001HP or 7007HP		9154	9066K	9066K	OBDII required
Mitsubishi	RVR (clamp-in)**	11-18	7001HP** or 7007HP**	5002 (Program first) or 5003M (Program first)	1051**	7020K	VS70	OBDII required
Mitsubishi	RVR (snap-in)**	13-20	7001HP-R** or 7007HP**	5002 (Program first) or 5003R (Program first)	5780	VS90	VS90	OBDII required
Mitsubishi	RVR	21-25	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	NEW	VS20	VS20	OBDII required
**	Note: Vehicle relearn will require an additional Mitsubishi-specific activation tool made by Bartec or Ateq.							
Nissan	350Z	03-06	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Nissan	350Z	07-09	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	370Z	09-10	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	370Z (Post June 2010)	10-20	7003A or 7007HP	5002' (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Altima	07-11	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Altima	12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Altima Coupe	13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Altima Sedan	13-18		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Nissan	Altima	19-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Nissan	Altima	21-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Nissan	ARIYA	23-25	7006HPR	5002 (Program first) or 5003R (Program first)	4762	VS20	VS20	OBDII required
Nissan	Armada (w/ Alloy wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Armada (w/ Steel wheels)	05-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Nissan	Armada	08-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Armada	17	7008HP	5001 (Program first) or 5003M (Program first)	1382	1100K	NO	OBDII required
Nissan	Armada	18-22	7006HPR	5002 (Program first) or 5003M (Program first)	1375	1100K	NO	OBDII required
Nissan	Armada	23-25	7006HPR	5002 (Program first) or 5003M (Program first)	1375	1100K	VS312	OBDII required
Nissan	Armada	25	7006HPR	5002 (Program first) or 5003R (Program first)	4761'	VS15	VS15	OBDII required
Nissan	Cube (w/out I-Key)	09-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Cube (w/out I-Key)	12-14	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	Cube (w/ I-Key)	11-12	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5557	7020K	VS70	OBDII required
Nissan	Cube (w/ I-Key)	12-14	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Frontier	03-04	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Nissan	Frontier (w/ Alloy wheels)	05-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Frontier (w/ Steel wheels)	05-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Nissan	Frontier	08-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Frontier	12-19	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Frontier (snap-in)	19	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	5362	VS90	VS90	OBDII required
Nissan	Frontier	20-21		5001 (Program first) or 5003R (Program first)	5564	VS20	VS20	OBDII required
Nissan	Frontier	22-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Nissan	GT-R	09-20	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	GT-R	21	7001HP or 7007HP	5002' (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	GT-R	23-24	7006HPR	5002' (Program first) or 5003M (Program first)	1375	1100K	VS312	OBDII required
Nissan	Juke Base (w/out I-Key <3/12)	11	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Juke SV & SL (w/ I-Key-- 7/10 - 7/11)	11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Juke (w/ I-Key-- 7/11 - 9/11)	11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5557	7020K	VS70	OBDII required
Nissan	Juke Base (w/out I-Key--Post 3/12)	12-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	Juke (w/ I-Key--Post 2/12)	12-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Juke	16-17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Kicks	18-20	7008HP	5001 (Program first) or 5003R (Program first)	4750	VS30	VS30	OBDII required
Nissan	Kicks	21-24	7008HP	5001 (Program first) or 5003R (Program first)	4750	VS15	VS15	OBDII required
Nissan	Kicks Play (433MHz)	25	7008HP	5001 (Program first) or 5003R (Program first)	4750	VS15	VS15	OBDII required
Nissan	Kicks (315MHz)	25	7006HPR	5002 (Program first) or 5003R (Program first)	4761	VS15	VS15	OBDII required
Nissan	Leaf	11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Leaf	12-13	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Leaf	13-17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5557	7020K	VS70	OBDII required
Nissan	Leaf	18-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Nissan	Leaf	21-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Nissan	Maxima	07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Maxima	07-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Maxima	12-14	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Maxima	16-19		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Nissan	Maxima (snap-in)	19-23		5001 (Program first) or 5003R (Program first)	5564	VS20	VS20	OBDII required
Nissan	Murano	03-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Nissan	Murano	07-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Murano (Post Nov. 2011)	12-14	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	Murano	15-19		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Nissan	Murano (snap-in)	19-24		5001 (Program first) or 5003R (Program first)	5564	VS20	VS20	OBDII required
Nissan	Murano	25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Nissan	NV200	13-17	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	NV200	18-21	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	5362	VS90	VS90	OBDII required
Nissan	NV 1500/2500HD/3500HD	12-21		5002 (Program first) or 5003M (Program first)	9342	2030K	NO	OBDII required
Nissan	Pathfinder	03-04	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Nissan	Pathfinder (w/ Steel wheels)	04	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Nissan	Pathfinder	05-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Pathfinder	07-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Pathfinder	13-19		5001 (Program first) or 5003M (Program first)	5556	7020K	VS70	OBDII required
Nissan	Pathfinder (snap-in)	19-20		5001 (Program first) or 5003R (Program first)	5564	VS20	VS20	OBDII required
Nissan	Pathfinder	22-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS20	VS20	OBDII required
Nissan	Qashqai	17-23	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Nissan	Quest (w/ Steel wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Nissan	Quest (w/ Alloy wheels)	04-06	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Quest	07-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Quest	11-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1216	1100K	NO	OBDII required
Nissan	Quest	17	7003A or 7007HP	5002 (Program first) or 5003R (Program first)	1344	VS30	VS30	OBDII required
Nissan	Rogue	08-11	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Rogue	12-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	Rogue Select	14-15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Rogue clamp-in (433 MHz)	14-16	7008HP	5001 (Program first) or 5003M (Program first)	5559	7020K	VS70	OBDII required
Nissan	Rogue snap-in	16-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Nissan	Rogue	21-25	7006HPR	5002 (Program first) or 5003R (Program first)	4762	VS20	VS20	OBDII required
Nissan	Rogue Sport	17-22	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	5661	VS90	VS90	OBDII required
Nissan	Sentra (w/ Alloy wheels)	07-08	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Sentra	07-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Sentra (> 1/12)	12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	Sentra (w/out I-Key)	13-16	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Sentra (w/out I-Key)	17-19	7001HP or 7007HP	5002 (Program first) or 5003R (Program first)	5362	VS90	VS90	OBDII required
Nissan	Sentra (w/ I-Key; push-button)	13-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5557	7020K	VS70	OBDII required
Nissan	Sentra (w/ I-Key; push-button)	17-19	7003A or 7007HP	5002 (Program first) or 5003R (Program first)	5163	VS90	VS90	OBDII required
Nissan	Sentra (315MHz)	20-24	7006HPR	5002 (Program first) or 5003R (Program first)	4761	VS15	VS15	OBDII required
Nissan	Sentra (433MHz)	23-24	7008HP	5001 (Program first) or 5003R (Program first)	4750	VS15	VS15	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Nissan	Titan (w/ Alloy wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Titan (w/ Steel wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Nissan	Titan	07-14	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Titan	15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Titan XD	16	7008HP	5001 (Program first) or 5003M (Program first)	1382	1100K	NO	OBDII required
Nissan	Titan (all)	17-24	7008HP	5001 (Program first) or 5003M (Program first)	1382	1100K	NO	OBDII required
Nissan	Versa	07-11	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Versa Sedan	12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Versa Sedan S and SV	13-16	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Versa Sedan S and SV	17	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Sedan	18	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Sedan SL	13-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5557	7020K	VS70	OBDII required
Nissan	Versa Sedan SL	17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa (key-in ignition)	19	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa (push-button ign.)	19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa	20-22	7008HP	5001 (Program first) or 5003R (Program first)	4750	VS30	VS30	OBDII required
Nissan	Versa	23-25	7008HP	5001 (Program first) or 5003R (Program first)	4750	VS15	VS15	OBDII required
Nissan	Versa Hatchback (Post Jan. 2012)	12-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	1100K	NO	OBDII required
Nissan	Versa Note S/SR/SV	14-16	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Versa Note S/SR/SV	17	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Note (w/out I-Key)	18-19	7001HP-R or 7007HP	5002 (Program first) or 5003M (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Note SL	14-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5557	7020K	VS70	OBDII required
Nissan	Versa Note SL	17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa Note (w/ I-Key)	18-19	7003A or 7007HP	5002 (Program first) or 5003R (Program first)	5163	VS90	VS90	OBDII required
Nissan	Xterra	03-04	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9064	1080K	NO	OBDII required
Nissan	Xterra	05-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9161	1080K	NO	OBDII required
Nissan	Xterra (w/ Steel wheels)	05-07	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9069	1130K	NO	OBDII required
Nissan	Xterra (<10/13)	08-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Xterra	13-14	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	5555	7020K	VS70	OBDII required
Nissan	Xterra	15	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Nissan	Z	23-25	7006HPR	5002` (Program first) or 5003M (Program first)	1375	1100K	VS312	OBDII required
Plymouth	Prowler	97-01			8004	1077K	NO	Dealer OBD only
Polestar	3	25			NEW	VS20	VS20	
Pontiac	G3	09	7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	OBDII required
Pontiac	G5	08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	G5	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Pontiac	G6 (Pre-10/15/07)	08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	G6 (Post-10/15/07)	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Pontiac	G8	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Pontiac	Grand Prix	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Grand Prix	08	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Pontiac	Montana	08-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9158	1070K	NO	Trigger required
Pontiac	Solstice	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Torrent	07-09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Vibe	08-10	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Pontiac	Wave	08-10	7006HPR or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	OBDII required
Porsche	911	06-08		5003M (Program first)	9001	1090K	1092	No tools needed
Porsche	911 Turbo	09		5003M (Program first)	9001	1090K	1092	No tools needed
Porsche	911 (non-Turbo)	09-11		5003M (Program first)	9011	1090K	1092	No tools needed
Porsche	911 Turbo	10-11		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	911	12-16		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	911	17-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	911	25-26		5003M (Program first)	9597	1096	1096	Auto-relearn
Porsche	918 Spyder	15		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	Boxster	06-08		5003M (Program first)	9001	1090K	1092	No tools needed
Porsche	Boxster	09-11		5003M (Program first)	9011	1090K	1092	No tools needed
Porsche	Boxster	12-16		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	718 Boxster	17-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	Carrera GT	04-06		5003M (Program first)	9001	1090K	1092	No tools needed
Porsche	Cayenne	03-06			9005	1090K	1092	No tools needed
Porsche	Cayenne	08-10		5003M (Program first)	9011	1090K	1092	No tools needed
Porsche	Cayenne	11-14		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	Cayenne (non-EV)	15-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	Cayman	06-08		5003M (Program first)	9001	1090K	1092	No tools needed
Porsche	Cayman	09-10		5003M (Program first)	9011	1090K	1092	No tools needed
Porsche	Cayman	11-16		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	718 Cayman	17-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	Macan	15-26		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	Macan EV	24-26		5003M (Program first)	9597	1096	1096	Auto-relearn
Porsche	Panamera	10-11		5003M (Program first)	9011	1090K	1092	No tools needed
Porsche	Panamera	12-13		5003M (Program first)	9011	1096	1096	No tools needed
Porsche	Panamera	14-23		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	Panamera	24-26		5003M (Program first)	9597	1096	1096	Auto-relearn
Porsche	Taycan	20-24		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Porsche	Taycan	25-26		5003M (Program first)	9597	1096	1096	Auto-relearn
RAM	1500, 2500, 3500 pickup	11-13		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
RAM	1500, 2500, 3500 SRW	14-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	19-20	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	21-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6896	VS65	VS65`	Auto-relearn
RAM	1500 (DT)	19-26		5001 (Program first) or 5003R (Program first)	3199	VS950	VS950	Auto-relearn
RAM	2500, 3500 SRW	19-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6896	VS65	VS65	Auto-relearn
RAM	2500, 3500 SRW	25-26			NEW	VS20	VS20	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	14-18	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6815	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	19-24	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	6896	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	25-26			NEW	2030K	VS40	
RAM	3500 DRW (Outer Alloy Wheel Sensor)	14-18		5001` (Program first) or 5003M (Program first)	6829	VS35	VS35	Auto-relearn
RAM	3500 DRW (Outer Alloy Wheel Sensor)	19-24		5001` (Program first) or 5003M (Program first)	6846	VS35	VS35	Auto-relearn
RAM	3500 DRW (Outer Alloy Wheel Sensor)	25-26			NEW	NEW	NEW	
RAM	3500 DRW (Inner Rear Wheel Sensor)	14-18			6825	VS65	VS65	Auto-relearn
RAM	3500 DRW (Inner Rear Wheel Sensor)	19-24			6854	VS65	VS65	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

15

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
RAM	3500 DRW (Inner Rear Wheel Sensor)	25-26			NEW	2030K	VS40	
RAM	Ram 4500, 5500 (Outer Steel Wheel Sensor)	19-24			6924	VS969	VS969	Auto-relearn
RAM	Ram 4500, 5500 (Outer Alloy Wheel Sensor)	19-24			6935	VS35	VS35	Auto-relearn
RAM	Ram 4500, 5500 (Inner Rear Wheel Sensor)	19-24			NEW	VS969	VS969	Auto-relearn
RAM	Trailer TPMS	19-26			NEW	2030K (0.453	VS40'	No tools needed
RAM	Cargo Van (C/V)	12-15		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
RAM	Dakota	11	7001HP-R or 7007HP	5002 (Program first) or 5003R (Program first)	9308	VS950	VS950	Auto-relearn
RAM	Promaster	14-21		5001 (Just relearn) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
RAM	Promaster	22-26	7008HP	5001 (Just relearn) or 5003M (Program first)	2495	7020K	VS70	Auto-relearn
RAM	Promaster City	15-22		5001 (Just relearn) or 5003M (Program first)	9214	1100K	VS40	Auto-relearn
Rivian	EDV van (Amazon)	22-24		5003M (Program first)	7420	1096B	1096B'	Auto-relearn
Rivian	R1S	22-25		5003M (Program first)	7420	1096	1096	Auto-relearn
Rivian	R1T	22-25		5003M (Program first)	7420	1096	1096	Auto-relearn
Rolls Royce	Cullinan	19-24		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	
Rolls Royce	Dawn	16-17		5001 (Program first) or 5003M (Program first)	9012	1096	1096	
Rolls Royce	Dawn	18-21		5001 (Program first) or 5003M (Program first)	9017	1096	1096	
Rolls Royce	Drophead Coupe	09-14		5003M (Program first)	1027	1090K	1092 or 1094	
Rolls Royce	Drophead Coupe	15-17		5001 (Program first) or 5003M (Program first)	9012	1096	1096	
Rolls Royce	Ghost	10-11		5003M (Program first)	1027	1090K	1092 or 1094	
Rolls Royce	Ghost (Post Sept. 2010)	11-20		5001 (Program first) or 5003M (Program first)	9012	1096	1096	
Rolls Royce	Ghost	21-24		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	
Rolls Royce	Phantom	07-11		5003M (Program first)	1027	1090K	1092 or 1094	
Rolls Royce	Phantom	12-16		5001 (Program first) or 5003M (Program first)	9012	1096	1096	
Rolls Royce	Phantom	17-24		5001 (Program first) or 5003M (Program first)	9077	1100K	VS40	
Rolls Royce	Wraith	14-21		5001 (Program first) or 5003M (Program first)	9012	1096	1096	
Saab	9-3.	03-07		5001 (Program first) or 5003M (Program first)	9078	2010K	NO	Auto-relearn
Saab	9-3.	08-11		5001 (Program first) or 5003M (Program first)	9159	2010K	NO	Auto-relearn
Saab	9-4x	11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Saab	9-5.	08-09		5001 (Program first) or 5003M (Program first)	9159	2010K	NO	Auto-relearn
Saab	9-5.	10-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Saab	9-7X	07-09	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9116	1070K	NO	Trigger required
Saturn	Astra	08-09		5001 (Program first) or 5003M (Program first)	9078	2010K	NO	Auto-relearn
Saturn	Aura (<10/14/07)	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Saturn	Aura (>10/14/07)	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003M (Program first)	9153	VS950	VS950	Trigger required
Saturn	Outlook	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Saturn	Outlook	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Saturn	Sky	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
Saturn	Vue	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Scion	FR-S	13-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Scion	iM	16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Scion	iQ	12-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Scion	tC	07-16	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Scion	xB	08-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Scion	xD	08-14	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Smart	Fortwo	08-15		5001 (Just relearn) or 5003M (Program first)	9214	2030K	9066K	No tools needed
Smart	Fortwo	16-19	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	No tools needed
Subaru	Ascent	19-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	B9 Tribeca	06-07	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9081	1080K	NO	OBDII required
Subaru	BRZ	13-20	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Subaru	BRZ	22-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	OBDII required
Subaru	Crosstrek	16-17	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	Crosstrek and Sport	18-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	Forester	08-18	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	Forester	19-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	Impreza	08-16	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	Impreza	17-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	Legacy	07	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9081	1080K	NO	OBDII required
Subaru	Legacy	08-17	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	Legacy	18-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	Outback	05-08	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9081	1080K	NO	OBDII required
Subaru	Outback	08-17	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	Outback	18-26	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	Solterra	23-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Subaru	Tribeca	08-14	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	WRX & STI	15-21	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Subaru	WRX	22-25	7005HPR or 7008HP	5001 (Program first) or 5003R (Program first)	8023	VS20	VS20	OBDII required
Subaru	XV Crosstrek	13-15	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9203	VS950	VS950	OBDII required
Suzuki	Equator	09-12	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	9204	2030K	NO	OBDII required
Suzuki	Forenza	07-08	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Suzuki	Grand Vitara**	07-13		5002 (Program first) or 5003M (Program first)	9087	2010K	NO	Trigger required
Suzuki	Kizashi	10-13	7001HP or 7007HP	5002 (Program first) or 5003M (Program first)	1051	7020K	VS70	Trigger required
Suzuki	Reno	07-08	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003R (Program first)	9153	VS950	VS950	Trigger required
Suzuki	SX4**	07-13		5002 (Program first) or 5003M (Program first)	9087	2010K	NO	Trigger required
Suzuki	Verona	05-06		5002 (Program first) or 5003M (Program first)	9082	2010K	NO	Trigger required
Suzuki	XL-7	05-06		5002 (Program first) or 5003M (Program first)	9087	2010K	NO	Trigger required
Suzuki	XL-7	07-09	7001HP or 7007HP	5002 (Just relearn) or 5003M (Program first)	Discontinued	1050K	NO	Trigger required
**	Note: Vehicle relearn will require an additional Mitsubishi/Suzuki-specific activation tool made by Bartec.							
Tesla	Cybertruck	24-25			2547	VS490	VS490	Auto-relearn
Tesla	ALL (Baolong)	10-14		5001 (Program first) or 5003M (Program first)	2112	TP416L	TP416L	Auto-relearn
Tesla	Model S (Continental 433MHz)	12-21		5001 (Program first) or 5003M (Program first)	2168	7020K	VS70	Auto-relearn
Tesla	Model S (Bluetooth)	21-25			2547	VS490	VS490	Auto-relearn
Tesla	Model X	16-21		5001 (Program first) or 5003M (Program first)	2168	7020K	VS70	Auto-relearn
Tesla	Model X (Bluetooth)	21-25			2547	VS490	VS490	Auto-relearn
Tesla	Model Y	20-25			2547	VS490	VS490	Auto-relearn
Tesla	Model Y (Schrader sensor)	25-26			NEW		VS40B	Auto-relearn
Tesla	Model 3 (433MHz)	17-21		5001 (Program first) or 5003M (Program first)	2168	7020K	VS70	Auto-relearn
Tesla	Model 3 (Bluetooth - black)	21-23			2547	VS490	VS490	Auto-relearn
Tesla	Model 3 (Bluetooth - silver)	21-23			2547	2030K		Auto-relearn
Tesla	Model 3	24-25			2547	VS490	VS490	Auto-relearn
Tesla	Model 3 (Schrader sensor)	25			NEW		VS40B	Auto-relearn
Tesla	Roadster (VIN 001-500)	08-10		5003M (Program first)	9011	1096	1096	No tools needed
Toyota	4Runner	04-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	4Runner	18-19	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	4Runner	20-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Toyota	4Runner (clamp-in)	22	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	4Runner (snap-in)	22-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	86	17-20	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Avalon	07-12	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Avalon	13-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Avalon	16-18	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Avalon	19-20	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	Avalon (snap-in)	20-22	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	bZ4X	23-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Camry	07-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Camry	12-14	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Camry w/ centered speedometer	15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Camry LE (Lo-Line)	16-17	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Camry w/ centered colored screen	15	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Camry LE (Hi-Line)	16-17	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Camry non-LE	16-17	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Camry Hybrid (all trims)	16-17	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Camry	18	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Camry L, LE, Hybrid LE	19	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Camry (all other trims)	19	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	Camry (w/ steel wheels)	20-24	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	Camry (w/ alloy wheels)	20-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	C-HR	18-22	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Corolla	07-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Corolla (all)	14-18	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Corolla sedan	19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Corolla hatchback	19	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	OBDII required
Toyota	Corolla (non-GR) w/ alloy wheels	20-23	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	OBDII required
Toyota	Corolla models w/ steel wheels	20-24	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	OBDII required
Toyota	Corolla (non-GR) and Cross w/ alloys	24	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Corolla	25-26	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Crown	23-26	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Crown Signia	25		5003R (Program first)	2434	VS15	VS15	Trigger required
Toyota	FJ Cruiser	08-14	7002A** or 7007HP**	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	GR 86	22-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	OBDII required
Toyota	GR Corolla	23-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	Grand Highlander	24-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Highlander	07-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Highlander (w/ Smart Key)	14-19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Highlander (w/out Smart Key)	14-19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1225	1100K	NO	OBDII required
Toyota	Highlander	20-24	7006HPR	5002 (Program first) or 5003M (Program first)	7091	1100K	NO	Trigger required
Toyota	Highlander	24-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	Land Cruiser	06-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Land Cruiser	16-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Land Cruiser	24-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Matrix	08-13	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Mirai	16-20	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Mirai	21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	Mirai	21-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Prius	06-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Prius V	12-16	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Prius C	12-19	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Prius	16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Prius (all trims)	17-18	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	Prius	19-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Prius	22-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	OBDII required
Toyota	RAV4	06-12	7002A** or 7007HP**	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	RAV4 Electric Vehicle (EV)	13-14	7002A** or 7007HP**	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	RAV4 (w/ Smart Key)	13-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	RAV4 (w/ Smart Key)	16-18	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	RAV4 non-EV (Made in Japan w/out Smart Key)	13-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
Toyota	RAV4 non-EV (Made in N.A. w/out Smart Key)	13-15	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1225	1100K	NO	OBDII required
Toyota	RAV4 (w/out Smart Key)	16-18	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1225	1100K	NO	OBDII required
Toyota	RAV4 LE (Japan)	19-20	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	RAV4 LE (Japan)	21-23	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	RAV4 LE (N.America)	19-23	7006HPR	5002 (Program first) or 5003M (Program first)	7091	1100K	NO	Trigger required
Toyota	RAV4 LE (N.America)	24	7006HPR	5002 (Program first) or 5003M (Program first)	7091	2040K	VS925A	Trigger required
Toyota	RAV4 LE (w/ Steel wheels)	25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	RAV4 (Smart-Key)	19	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	RAV4 clamp-in (Smart-Key)	20	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	RAV4 clamp-in (Smart-Key)	21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	RAV4 (snap-in)	20-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Sequoia (w/ Alloy wheels)	05-07	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	Sequoia (w/ Steel wheels)	05-07	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1203 (OE)	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	Sequoia (20 Degrees)	08-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1206	1110K	NO	OBDII required
Toyota	Sequoia	18-19	7006HPR	5002 (Program first) or 5003M (Program first)	7091	1100K	NO	Trigger required
Toyota	Sequoia	20-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	Sequoia	22-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1241	VS15	VS15	Trigger required
Toyota	Sienna	07-20	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1206	1110K	NO	OBDII required
Toyota	Sienna (TRW)	21-24	7006HPR	5002 (Program first) or 5003M (Program first)	7091	2040K	VS925A	Trigger required
Toyota	Sienna (Pacific)	24-25	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	VS312	Trigger required
Toyota	Solara	07-08	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Supra	20-26		5001 (Program first) or 5003M (Program first)	9077	1096	1096	
Toyota	Tacoma (w/ Alloy wheels)	05-06	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE)	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	Tacoma (w/ Steel wheels)	05-15	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1203 (OE)	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	Tacoma (w/ Steel wheels)	16-23	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	NEW			OBDII required
Toyota	Tacoma (w/ Alloy wheels)	07-15	7002A** or 7007HP**	5002 (Program first) or 5003M (Program first)	1204 (OE)	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Tacoma (w/ Alloy wheels)	16-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	OBDII required
Toyota	Tacoma (snap-in)	21-23	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1241	VS15	VS15	OBDII required
Toyota	Tacoma	24-26	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Tundra (w/ Alloy wheels)	05-06	7002A** or 7007HP**	5002 (Program first) or 5003M (Program first)	1204 (OE)	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	Tundra (w/ Steel wheels)	05-06	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1203 (OE)	1110K (OE), 2	None (OE), 1096	OBDII required
Toyota	Tundra (40 Degrees)	07-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1206	1110K	NO	OBDII required
Toyota	Tundra (20 Degrees)	07-17	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1206	1110K	NO	OBDII required
Toyota	Tundra (w/ Alloy wheels)	18-19	7006HPR	5002 (Program first) or 5003M (Program first)	7091	1100K	NO	Trigger required
Toyota	Tundra (RKE w/ Alloy wheels)	20-21	7006HPR	5002 (Program first) or 5003M (Program first)	7091	1100K	NO	Trigger required
Toyota	Tundra (Smart-Key w/ clamp-in)	20-21	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	1230	1100K	NO	Trigger required
Toyota	Tundra (Smart-Key w/ snap-in)	21	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

17

DILL TPMS APPLICATIONS CHART ©

What's In Your Tires?®

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Toyota	Tundra (w/ Steel wheels)	18-21	7006HPR	5002 (Program first) or 5003M (Program first)	7114	1100K	NO	Trigger required
Toyota	Tundra	22-25	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Venza	09-16	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Venza	21-24	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	1241	VS15	VS15	Trigger required
Toyota	Yaris	08-11	7002A or 7007HP	5002 (Program first) or 5003M (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Toyota	Yaris	12-18	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1218	1100K	NO	OBDII required
**	Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).							
Volkswagen	Arteon	19-23		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Volkswagen	Atlas and Cross Sport	24-25		5001 (Program first) or 5003M (Program first)	9018	1096	1096	Auto-relearn
Volkswagen	Beetle	08-10	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required
Volkswagen	CC	09-11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	CC	12-17		5001 (Program first) or 5003M (Program first)	9013	1096	1096	No tools needed
Volkswagen	Eos	07-16	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	Golf	10-11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	GTI	06-11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	GTI w/ OE 18in wheels	06-07	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1041	1031K	NO	Trigger required'
Volkswagen	Jetta	06-11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	Passat	06-10	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	Passat w/ OE 18in wheels	06-08	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1041	1031K	NO	Trigger required'
Volkswagen	Phaeton	04-06		5003M (Program first)	9001	1090K	1092	No tools needed
Volkswagen	R32	08	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	Rabbit	07-09	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	Routan	09-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1043	1050K	NO	Auto-relearn
Volkswagen	Routan	11-14		5001 (Just relearn) or 5003R (Program first)	9398	VS950	VS950	Auto-relearn
Volkswagen	Tiguan	09-11	7003A or 7007HP	5002 (Program first) or 5003M (Program first)	1053	1030K	NO	Trigger required'
Volkswagen	Tiguan	14		5001 (Program first) or 5003M (Program first)	9013	1096	1096	No tools needed
Volkswagen	Touareg	04-07			9005	1090K	1092	No tools needed
Volkswagen	Touareg	08-10		5003M (Program first)	9011	1090K	1092	No tools needed
Volkswagen	Touareg	11-14		5003M (Program first)	9011	1096	1096	No tools needed
Volkswagen	Touareg	15-17		5001 (Program first) or 5003M (Program first)	9018	1096	1096	No tools needed
Volvo	C30	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K	NO	Auto-relearn
Volvo	C30	10-13	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	C70	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K	NO	Auto-relearn
Volvo	C70	10-13	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	EX90	25			NEW	VS20	VS20	Auto-relearn
Volvo	S40	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K	NO	Auto-relearn
Volvo	S40	10-11	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S60	05-08	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9156	2010K	NO	Auto-relearn
Volvo	S60	08-09	7004 or 7006HPR	5002 (Program first) or 5003R (Program first)	9156	VS950	VS950	Auto-relearn
Volvo	S60	11-13	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S60 (clamp-in)	14-17		5001 (Program first) or 5003M (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	S80	05-06	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9156	2010K	NO	Auto-relearn
Volvo	S80	07-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K	NO	Auto-relearn
Volvo	S80	10-13	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S80 (clamp-in)	14-16		5001 (Program first) or 5003M (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	V50	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K	NO	Auto-relearn
Volvo	V50	10-11	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	V60 (clamp-in)	15-18		5001 (Program first) or 5003M (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	V70	05-07	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9156	2010K	NO	Auto-relearn
Volvo	V70	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K or 7020K	None or VS70	Auto-relearn
Volvo	XC60	10-13	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	XC60	14-17		5001 (Program first) or 5003M (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	XC70	05-07	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9156	2010K	NO	Auto-relearn
Volvo	XC70	08-10	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	1050K	NO	Auto-relearn
Volvo	XC70	10-13	7004 or 7008HP	5001 (Program first) or 5003M (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	XC70 (clamp-in)	14-16		5001 (Program first) or 5003M (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	XC90 (315 MHz)	05-08	7003A or 7006HPR	5002 (Program first) or 5003M (Program first)	9156	2010K	NO	Auto-relearn
Volvo	XC90 (315 MHz)	08-14	7003A or 7006HPR	5002 (Program first) or 5003R (Program first)	9156	VS950	VS950	Trigger required
Volvo	XC90 (Direct TPMS)	16-17	7008HP	5001 (Program first) or 5003R (Program first)	NEW	VS20	VS20	Auto-relearn
VPG	MV-1	11-17	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003R (Program first)	9315	VS950	VS950	Trigger required

DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. ***PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.***

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

18