315 MHz Dill 5002 Sensor

Covers over 115 million vehicles including the *Tahoe, F150, and Camry*

&

Replaces 65 OEM sensors including 1204, 9204, 9315

- ⇒ Pre-programmed as 9153 / 6164 (26% of 315 MHz applications)
- ⇒ Comes with VS-20 rubber valve stem
- ⇒ Interchangeable valve design allows corrosion-resistant VS-240 valve stem to be used
- ⇒ Works with Bartec and Ateq tools
- ⇒ Future proof with tool software updates



A T E Q

VT56



If programming, make sure your tool is updated to latest software version, then:

- 1. Select "Program"
- 2. Select "Make"
- 3. Pick your vehicle
- Select "Dill 5001 or 5002"
- Select "Create"
- 6. Follow onscreen prompts

B A R T



If programming, make sure your tool is updated to latest software version, then:

- 1. Select "New TPMS Service"
- 2. Pick your vehicle
- 3. Select "Program Sensors"
- 4. Select "Dill 5001 or 5002"
- 5. Select "Create ID"
- 6. Follow onscreen prompts



C

*For free make/model/year parts and relearn lookup, visit www.DillValves.com

