

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Acura	CSX	08-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Acura	ILX	13-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5513	7000K	VS70	OBDII required
Acura	ILX	16-18	7007HP		5514	7000K	VS70	Auto-relearn
Acura	ILX	19-22		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	Integra (snap-in)	23-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	Integra Type S	24-25		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	MDX	04-06	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Acura	MDX	07-13	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	MDX	14-15			5512	7000K	VS70	Auto-relearn
Acura	MDX	16-20	7007HP		5514	7000K	VS70	Auto-relearn
Acura	MDX	22-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	NSX	16-22		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	RDX	07-12	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	RDX	13-15			5512	7000K	VS70	Auto-relearn
Acura	RDX	16-18	7007HP		5514	7000K	VS70	Auto-relearn
Acura	RDX (clamp-in)	19-21		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	RDX (snap-in)	21-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	RL	05-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Acura	RL	09-12	7002A or 7007HP		1057	2045K or 2000K	None or 1096	Auto-relearn
Acura	RLX	14-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1214	2045K	NO	Auto-relearn
Acura	RLX	16-20			5512	7000K	VS70	Auto-relearn
Acura	TL	06-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Acura	TL	09-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1214	2045K	NO	Auto-relearn
Acura	TLX	15-17	7007HP		5514	7000K	VS70	Auto-relearn
Acura	TLX	18-20		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	TLX	21-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	TSX	07-14	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	ZDX	10-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1214	2045K	NO	Auto-relearn
Acura	ZDX	24			3166	VS20	VS20	Auto-relearn
Alfa Romeo	4C	15-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
Alfa Romeo	8C Competizione	09-10		5003 (Program first)	9001	1090K	1092 or 1094	
Alfa Romeo	Giulia	17-24	7008HP	5001 (Program first) or 5003 (Program first)	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Stelvio	18-24	7008HP	5001 (Program first) or 5003 (Program first)	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Tonale	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Aston Martin	DBX	21-25		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Trigger required
Aston Martin	Vantage	19-21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
Audi	Allroad	02-05		5003 (Program first)	9004	1090K	1092 or 1099L	No tools needed
Audi	A3	08-11	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	A4	05-08		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	A4 cabrio	09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	A4 4-door	09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	A5	08-09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	A6	05-08		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	A6 (clamp-in)	22-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	A7 (clamp-in)	22-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	A8	02-03		5003 (Program first)	9004	1090K	1092	No tools needed
Audi	A8	04-09		5003 (Program first)	9001	1090K	1092	No tools needed
Audi	A8 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	e-tron crossover (clamp-in)	22-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	e-tron GT sedan	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	Q5	09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	Q7	07-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	Q7 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	Q8 and Q8 e-tron (clamp-in)	22-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	R8	08-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	R8	10-23		5003 (Program first)	9011	1096	1096	No tools needed
Audi	RS3	17-20		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS3	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS4	07-08		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	RS5	18-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS6	03		5003 (Program first)	9004	1090K	1092	No tools needed
Audi	RS6	21-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS7	14-18		5003 (Program first)	9011	1096	1096	No tools needed
Audi	RS7	21-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS e-tron GT	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS Q8	20-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	S4	05-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	S5	08-09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	S6	07-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	S6 (clamp-in)	22-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	S7 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	S8	02-03		5003 (Program first)	9004	1090K	1092	No tools needed
Audi	S8	07-09		5003 (Program first)	9001	1090K	1092	No tools needed
Audi	S8	16-18		5003 (Program first)	9011	1096	1096	No tools needed
Audi	S8	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	SQ5	14-16		5003 (Program first)	9011	1096	1096	No tools needed
Audi	SQ7 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	SQ8 (non-RS)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	TT	08-10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	TT RS	18-22		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Bentley	Arnage	02-03		5003 (Program first)	9001	1090K	1092-1095	
Bentley	Arnage	04-09		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Azure	07-10		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Bentayga	17-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	
Bentley	Brooklands Coupe	08-09		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Continental GT	04-05		5003 (Program first)	9001	1090K	1092-1095	
Bentley	Continental GT (Post May 2005)	05-10		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Continental GT	11-18		5003 (Program first)	9011	1096	1096	
Bentley	Continental GT	20-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	
Bentley	Continental GT	25			9597	1096	1096	
Bentley	Flying Spur	06-10		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Flying Spur	11-18		5003 (Program first)	9011	1096	1096	
Bentley	Flying Spur	20-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	
Bentley	Flying Spur	25			9597	1096	1096	
Bentley	Mulsanne	11-20		5003 (Program first)	9011	1096	1096	
BMW	1 Series	08-11		5003 (Program first)	1027	1090K	1092-1095	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support



(Row Color designates the required replacement parts kit for the OE sensor.)

Table with columns: Make, Model, Model Year Range, Dill REDI-Sensor Sensor, Dill 5000-Series Sensor, Dill OE Sensor, Dill OE Kit, Dill OE Valve Stem, Simplified Relearn. Rows include various car models like Buick Verano, Cadillac ATS, Chevrolet Aveo, etc.

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support







(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
GMC	Acadia	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Acadia Limited	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Acadia	17	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
GMC	Acadia	18-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Acadia	24-25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Canyon	07-12	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
GMC	Canyon	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Canyon	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Canyon	20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Canyon	21-22			2346	VS20	VS20	Auto-relearn
GMC	Canyon	23-25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Envoy	06-09	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
GMC	Hummer EV	22-25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Savana	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
GMC	Savana	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Savana (SRW)	17-25	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Sierra 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	18	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra Limited	19	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra 1500	19-21	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra 1500 Limited	22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra 1500 (facelifted)	22-25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Sierra 2500/3500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Sierra 2500/3500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 2500/3500	18-19	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra HD (SRW)	20-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra HD (SRW)	24-25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Sierra 3500HD DRW (Front alloy wheel)	20-23		5001 (Program first) or 5003 (Program first)	7659	DA543E	DA543E	Trigger required
GMC	Sierra 3500HD DRW (Front alloy wheel)	24-25		5003 (Program first)	7624	DA543E	DA543E	Trigger required
GMC	Sierra 3500HD DRW (Front steel wheel)	20-23	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Front steel wheel)	24-25		5003 (Program first)	8424	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Rear wheels)	20-23	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Rear wheels)	24-25		5003 (Program first)	8424	2030K	VS40	Trigger required
GMC	Sierra Trailer TPMS	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
GMC	Terrain	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Terrain	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Terrain	18-21	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Terrain	22-24	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	2346	VS20	VS20	Trigger required
GMC	Terrain	25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Trailer TPMS	21-25	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
GMC	Yukon 1500	04		5002 (Program first) or 5003 (Program first)	9115	1070K	NO	Trigger required
GMC	Yukon 1500	05-06	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9107	1070K	NO	Trigger required
GMC	Yukon	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinue	2020K	NO	Trigger required
GMC	Yukon	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
GMC	Yukon 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinue	2020K	NO	Trigger required
GMC	Yukon 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
GMC	Yukon	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Yukon 2500	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Yukon	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Yukon	18-20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Yukon	21-25		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Honda	Accord	08-12	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Honda	Civic	08-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	CR-V	07-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Honda	CR-V	12-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5511	7020K	VS70	OBDII required
Honda	CR-Z	11-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Crosstour	10-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5511	7020K	VS70	OBDII required
Honda	Element	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Honda	Element	09-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Fit	08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Honda	Fit	09-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Insight	10-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Odyssey EX, EX-L, LX	07	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Honda	Odyssey EX, EX-L, LX	08-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2045K or 2000K	None or 1096	OBDII required
Honda	Odyssey Touring	05-07	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Honda	Odyssey Touring	08-10	7002A or 7007HP		1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Odyssey and Touring	11-17	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Odyssey	18-20		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Odyssey	21-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	Passport	19-21		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Passport	22-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	Pilot (Steel Wheels)	05-08	7002A or 7007HP		1059	2000K	1097	Auto-relearn
Honda	Pilot (Alloy Wheels)	05-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Honda	Pilot (Alloy Wheels)	09-15	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Honda	Pilot (Steel Wheels)	09-15	7002A or 7007HP		1219	1100K	NO	Auto-relearn
Honda	Pilot	16-22		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Pilot	23-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	Prologue	24			3166	VS20	VS20	Auto-relearn
Honda	Ridgeline (Steel Wheels)	06-08	7002A or 7007HP		1059	2000K	1097	Auto-relearn
Honda	Ridgeline (Alloy Wheels)	06-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Honda	Ridgeline	09-14	7002A or 7007HP		1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Ridgeline	17-20		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Ridgeline	21-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	S2000	08-09	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Hummer	H2	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Hummer	H3	06-10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
Hummer	H3T	09-10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©



(Row Color designates the required replacement parts kit for the OE sensor.)

Table with columns: Make, Model, Model Year Range, Dill REDI-Sensor Sensor, Dill 5000-Series Sensor, Dill OE Sensor, Dill OE Kit, Dill OE Valve Stem, Simplified Relearn. Contains data for various car models like Hyundai Accent, Elantra, etc., and Infiniti models.

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dilvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos. Need Additional Help? Call 800-815-3455, option 3 for technical support



(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Infiniti	QX60 (snap-in)	20		5001 (Program first) or 5003 (Program first)	5564	VS20	VS20	OBDII required
Infiniti	QX60	22-25	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS20	VS20	OBDII required
Infiniti	QX70	14-17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX80	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX80	17	7008HP	5001 (Program first) or 5003 (Program first)	1382	1100K	NO	OBDII required
Infiniti	QX80	18-22	7006HPR	5002 (Program first) or 5003 (Program first)	1375	1100K	NO	OBDII required
Infiniti	QX80	23-24	7006HPR	5002 (Program first) or 5003 (Program first)	1375	1100K	VS312	OBDII required
Infiniti	QX80	25	7006HPR	5002 (Program first) or 5003 (Program first)	4761	VS15	VS15	OBDII required
Isuzu	Ascender	06-08	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Isuzu	I-series pickup	07-08	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
Isuzu	Rodeo	04			9028	1080K	NO	Dealer OBD only
Jaguar	E-Pace	18-21	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	E-Pace	22-24	7008HP	5001 (Program first) or 5003 (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	F-Pace	17-21	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	F-Pace	22-25	7008HP	5001 (Program first) or 5003 (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	F-Type (315MHz)	14-15		5002 (Program first) or 5003 (Program first)	1045	7020K	VS70	Auto-relearn
Jaguar	F-Type (433MHz Export)	14			1046	1050K	NO	Auto-relearn
Jaguar	F-Type (433MHz)	15-24	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	I-Pace (clamp-in)	19-22	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	I-Pace (snap-in)	22-24	7008HP	5001 (Program first) or 5003 (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	X-Type (315MHz)	08		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	X-Type (433MHz Export)	08			1046	1050K	NO	Auto-relearn
Jaguar	XE	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XF (315MHz)	09-16		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XF (433MHz Export)	09-15			1046	1050K	NO	Auto-relearn
Jaguar	XF (433MHz)	16-24	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XJ (315MHz)	06-09		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	10-11		5002 (Program first) or 5003 (Program first)	1045	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz Export)	06-11			1046	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	12-16		5002 (Program first) or 5003 (Program first)	1045	1050K or 7020K	None or VS70	Auto-relearn
Jaguar	XJ (433MHz Export)	12-14			1046	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz)	15-19	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XK (315MHz)	07-15		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XK (433MHz Export)	07-15			1046	1050K	NO	Auto-relearn
Jeep	Cherokee	14-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
Jeep	Cherokee	19-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
Jeep	Commander	06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Commander	07	7001HP or 7007HP		1051	9066K	9066K	Auto-relearn
Jeep	Commander	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Compass	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Compass	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Jeep	Compass (315MHz)	13-17	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz Export)	13-14			9481	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz)	17-25	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Gladiator	20-21		5001 (Program first) or 5003 (Program first)	4665	VS950	VS950	Auto-relearn
Jeep	Gladiator (built on or after 6/7/2021)	21-25		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee	02-04	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Jeep	Grand Cherokee	05-06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Grand Cherokee	07	7001HP or 7007HP		1051	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	11-15		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Grand Cherokee	16	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS90	VS90	Auto-relearn
Jeep	Grand Cherokee (non-L)	17-21	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee (WK)	22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee L	21		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee (New) and L	22-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee and L	24-25			NEW	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee SRT8	12-15		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee SRT	16-21	7008HP	5001 (Program first) or 5003 (Program first)	2495	7020K	VS70	Auto-relearn
Jeep	Grand Wagoneer	22-23		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Wagoneer	24-25			NEW	VS20	VS20	Auto-relearn
Jeep	Liberty	04	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Jeep	Liberty	05-06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Liberty	07-10	7001HP or 7007HP		1051	9066K	9066K	Auto-relearn
Jeep	Liberty	10-12	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Liberty (433MHz Export)	07-09	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Liberty (433MHz Export)	10-12			9481	VS950	VS950	Auto-relearn
Jeep	Patriot	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Patriot	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Jeep	Patriot	13-17	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Patriot (433MHz Export)	12-14			9481	VS950	VS950	Auto-relearn
Jeep	Renegade	15-16	7008HP	5001 (Program first) or 5003 (Program first)	5775	VS90	VS90	Auto-relearn
Jeep	Renegade	17-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Wagoneer	22-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Wagoneer	24-25			NEW	VS20	VS20	Auto-relearn
Jeep	Wrangler	07-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1051	9066K	9066K	Auto-relearn
Jeep	Wrangler (433MHz Export)	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Wrangler	10-12	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	9308	VS950	VS950	Auto-relearn
Jeep	Wrangler (433MHz Export)	10-12		5001 (Program first) or 5003 (Program first)	9481	VS950	VS950	Auto-relearn
Jeep	Wrangler (JK)	13-18		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler (JL)	18-20		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler	21		5001 (Program first) or 5003 (Program first)	4665	VS950	VS950	Auto-relearn
Jeep	Wrangler (built on or after 6/7/2021)	21-25		5003 (Program first)	3996	VS20	VS20	Auto-relearn
KIA	Amanti	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
KIA	Amanti	09	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
KIA	Borrego	09-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
KIA	Cadenza	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
KIA	Cadenza	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
KIA	Camival	22-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
KIA	Camival	25			NEW	VS20	VS20	OBDII required
KIA	EV6 (snap-in)	22-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
KIA	EV6 GT (clamp-in)	23-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	1100K	VS40	OBDII required
KIA	EV9	24			NEW	VS20	VS20	OBDII required
KIA	Forte	10-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	7020K	VS70	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Table with 9 columns: Make, Model, Model Year Range, Dill REDI-Sensor, Dill 5000-Series Sensor, Dill OE Sensor, Dill OE Kit, Dill OE Valve Stem, and Simplified Relearn. Rows include vehicles from KIA, Lamborghini, Land Rover, and Lexus.

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support





(Row Color designates the required replacement parts kit for the OE sensor.)


Table with columns: Make, Model, Model Year Range, Dill REDI-Sensor Sensor, Dill 5000-Series Sensor, Dill OE Sensor, Dill OE Kit, Dill OE Valve Stem, Simplified Relearn. Rows include various vehicles like Mercedes-Benz, Mercury, Mini, Mitsubishi, and Nissan with their respective sensor and relearn information.

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dilvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support



# DILL TPMS APPLICATIONS CHART ©



(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Nissan	Versa Note S/SR/SV	17	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Note (w/out I-Key)	18-19	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Note SL	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5557	7020K	VS70	OBDII required
Nissan	Versa Note SL	17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa Note (w/ I-Key)	18-19	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Xterra	03-04	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Nissan	Xterra	05-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Xterra (w/ Steel wheels)	05-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9069	1130K	NO	OBDII required
Nissan	Xterra (<10/13)	08-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Xterra	13-14	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Xterra	15	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Z	23-24	7006HPR	5002 (Program first) or 5003 (Program first)	1375	1100K	VS312	OBDII required
Plymouth	Prowler	97-01			8004	1077K	NO	Dealer OBD only
Pontiac	G3	09	7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	OBDII required
Pontiac	G5	08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	G5	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	G6 (Pre-10/15/07)	08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	G6 (Post-10/15/07)	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	G8	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	Grand Prix	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Grand Prix	08	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	Montana	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Pontiac	Solstice	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Torrent	07-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Vibe	08-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Pontiac	Wave	08-10	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	OBDII required
Porsche	911	06-08		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	911 Turbo	09		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	911 (non-Turbo)	09-11		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	911 Turbo	10-11		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	911	12-16		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	911	17-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	918 Spyder	15		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	Boxster	06-08		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	Boxster	09-11		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Boxster	12-16		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	718 Boxster	17-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Carrera GT	04-06		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	Cayenne	03-06			9005	1090K	1092	No tools needed
Porsche	Cayenne	08-10		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Cayenne	11-14		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	Cayenne	15-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Cayman	06-08		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	Cayman	09-10		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Cayman	11-16		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	718 Cayman	17-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Macan	15-25		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Macan EV	24-25			9597	1096	1096	Auto-relearn
Porsche	Panamera	10-11		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Panamera	12-13		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	Panamera	14-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Panamera	24			9597	1096	1096	Auto-relearn
Porsche	Taycan	20-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Taycan	25			9597	1096	1096	Auto-relearn
RAM	1500, 2500, 3500 pickup	11-13		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
RAM	1500, 2500, 3500 SRW	14-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	21-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
RAM	1500 (DT)	19-24		5001 (Program first) or 5003 (Program first)	3199	VS950	VS950	Auto-relearn
RAM	1500	25		5001 (Program first) or 5003 (Program first)	3199	VS950	VS950	Auto-relearn
RAM	2500, 3500 SRW	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	14-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Alloy Wheel Sensor)	14-18		5001 (Program first) or 5003 (Program first)	6829	VS35	VS35	Auto-relearn
RAM	3500 DRW (Outer Alloy Wheel Sensor)	19-24		5001 (Program first) or 5003 (Program first)	6846	VS35	VS35	Auto-relearn
RAM	3500 DRW (Inner Rear Wheel Sensor)	14-18			6825	VS65	VS65	Auto-relearn
RAM	3500 DRW (Inner Rear Wheel Sensor)	19-24			6854	VS65	VS65	Auto-relearn
RAM	Ram 4500, 5500 (Outer Steel Wheel Sensor)	19-24			6924	VS969	VS969	Auto-relearn
RAM	Ram 4500, 5500 (Outer Alloy Wheel Sensor)	19-24			6935	VS35	VS35	Auto-relearn
RAM	Ram 4500, 5500 (Inner Rear Wheel Sensor)	19-24			NEW	VS969	VS969	Auto-relearn
RAM	Trailer TPMS	19-25			NEW	2030K (0.453)	VS40	No tools needed
RAM	Cargo Van (C/V)	12-15		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
RAM	Dakota	11	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	9308	VS950	VS950	Auto-relearn
RAM	Promaster	14-21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
RAM	Promaster	22-24	7008HP	5001 (Program first) or 5003 (Program first)	2495	7020K	VS70	Auto-relearn
RAM	Promaster City	15-22		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
Rivian	EDV van (Amazon)	22-24		5003 (Program first)	7420	1096B	1096B	Auto-relearn
Rivian	R1S	22-24		5003 (Program first)	7420	1096	1096	Auto-relearn
Rivian	R1T	22-24		5003 (Program first)	7420	1096	1096	Auto-relearn
Rolls Royce	Cullinan	19-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Auto-relearn
Rolls Royce	Dawn	16-17		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Dawn	18-21		5001 (Program first) or 5003 (Program first)	9017	1096	1096	Auto-relearn
Rolls Royce	Drophead Coupe	09-14		5003 (Program first)	1027	1090K	1092 or 1094	Auto-relearn
Rolls Royce	Drophead Coupe	15-17		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Ghost	10-11		5003 (Program first)	1027	1090K	1092 or 1094	Auto-relearn
Rolls Royce	Ghost (Post Sept. 2010)	11-20		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Ghost	21-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Auto-relearn
Rolls Royce	Phantom	07-11		5003 (Program first)	1027	1090K	1092 or 1094	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support





(Row Color designates the required replacement parts kit for the OE sensor.)

Table with columns: Make, Model, Model Year Range, Dill REDI-Sensor Sensor, Dill 5000-Series Sensor, Dill OE Sensor, Dill OE Kit, Dill OE Valve Stem, Simplified Relearn. Rows include Toyota (Corolla, Camry, RAV4, etc.), Volkswagen (Beetle, Golf, etc.), and others.

Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Volkswagen	Routan	09-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Volkswagen	Routan	11-14		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Volkswagen	Tiguan	09-11	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Volkswagen	Tiguan	14		5001 (Program first) or 5003 (Program first)	9013	1096	1096	No tools needed
Volkswagen	Touareg	04-07			9005	1090K	1092	No tools needed
Volkswagen	Touareg	08-10		5003 (Program first)	9011	1090K	1092	No tools needed
Volkswagen	Touareg	11-14		5003 (Program first)	9011	1096	1096	No tools needed
Volkswagen	Touareg	15-17		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Volvo	C30	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	C30	10-13	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	C70	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	C70	10-13	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S40	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	S40	10-11	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S60	05-08	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	S60	08-09	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	VS950	VS950	Auto-relearn
Volvo	S60	11-13	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S60 (clamp-in)	14-17		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	S80	05-06	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	S80	07-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	S80	10-13	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	S80 (clamp-in)	14-16		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	V50	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	V50	10-11	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	V60 (clamp-in)	15-18		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	V70	05-07	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	V70	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K or 7020K	None or VS70	Auto-relearn
Volvo	XC60	10-13	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	XC60	14-17		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	XC70	05-07	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	XC70	08-10	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	XC70	10-13	7004 or 7008HP	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	XC70 (clamp-in)	14-16		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	XC90 (315 MHz)	05-08	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	XC90 (315 MHz)	08-14	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	VS950	VS950	Trigger required
Volvo	XC90 (Direct TPMS)	16-17		5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	Auto-relearn
VPG	MV-1	11-13	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required

**DISCLAIMER:** The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. **PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.**

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos  
Need Additional Help? Call 800-815-3455, option 3 for technical support