## **DRAFT**

## Only for computers missing of COM port: Connect the BT2 antenna to the computer by USB

	Operations	Description (foto)
1	Make Sure that there is <u>NO</u> Jumper on the Antenna when using it with a USB connection	
2	Plug the Antenna into any USB Port of your Computer	Connect To USB Port
		Found New Hardware  Windows needs to install driver software for your USB Serial
3	After you Plug in the Antenna, a Window will appear (Picture). Click on the indicated Option	Port  Don't show this message again for this device Your device will not function until you install driver software.  Cancel







